



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21012805/Atf3e2 Date: 18/01/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKK 767H	Veh. Inspected	SLX 8631H	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10012980/KY	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	20/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MR053REH104554519	Colour	GREY	
Odometer	88772 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	MICHELIN	6 mm	
L/H Front Tyre	215/45 R17	MICHELIN	6 mm	
R/H Rear Tyre	215/45 R17	MICHELIN	6 mm	
L/H Rear Tyre	215/45 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/12/2021	Inspection Date	20/12/2021	
Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			18 Working Days	