

China Wsum

COMFORTDELGRO ENGINEERING PTE LTD

Date: 10.12.2021

REPAIR ESTIMATE

Time: 14:09:34

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305497465  
REGN NO : SHD6725L ✓  
MILEAGE : 0000000000 ✓  
MAKE : MERCEDES BENZ  
MODEL : E220CDI(E6)  
DATE OF REGN : 08.04.2016  
DATE/TIME IN : 10.12.2021 12:55  
ACCIDENT DATE : 10.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0202-2292-G FRONT BUMPER ASSY 1 1,890.50 20.00 1,512.40 ✓  
0002 04-01-0202-0582-G RADIATOR GRILLE 1 1,220.00 20.00 976.00 / CRA  
0003 28-01-0202-2028-A VEHICLE NUMBER PLATE FRON 1 N 50.00 2.00- 50.00 / SCR

SUB-TOTAL : 2,538.40 ✓

JOB NATURE

0000 PB PANEL BEATING 500.00 400  
0001 SP SPRAYPAINT CHARGE 300.00 250  
0002 17-01 CHECK ALL LIGHTING 50.00 20 ✓  
SUB-TOTAL : 850.00

TOTAL : 3,388.40

Juman!

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

Thuan @LKKauto.com  
82235769  
10/12/21 1600  
L/S after repair photo  
2 days up ✓

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 10.12.2021 14:05

Page : 1

am: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 4150337

JC NO305497465

OMER

IS COMFORT TRANSPORTATION PTE LTD

OMER NO. 7010045

ESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

DUNT CARD NO.

REGN NO:

SHD6725L

MILEAGE

MAKE:

MERCEDES BENZ

FUEL

E.....1/2.....F

MODEL

E220CDI (E6)

DATE/TIME IN 10.12.2021 12:55

YR OF MANU.

08.04.2016

TARGET DATE

CHASSIS CODE

WDD2120012B318791

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 10.12.2021

ATURE: 3P.10.12.2021

NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Io.: SHD6725L

JU CHINA

Vehicle No.:

SHD6725L

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard