



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: OH VALE			Ref: CS/ASM21012839/Kty3e2 Date: 31/12/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	SHA 4293U	Veh. Inspected	SMF 3084C
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S1M03MP9	Excess (\$)	0.00
	Assign From	OH VALE	Assign Date	20/12/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	RU31303486	Colour	METALLIC PEARL RED
	Odometer	63697 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	YOKOHAMA	9 mm
	L/H Front Tyre	215/60 R16	YOKOHAMA	9 mm
	R/H Rear Tyre	215/60 R16	YOKOHAMA	9 mm
	L/H Rear Tyre	215/60 R16	YOKOHAMA	9 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	21/11/2021	Inspection Date	22/12/2021
	Survey held at	AESOP AUTOMOTIVE CENTRE BLK 5032 #01-299 ANG MO KIO IND PARK 2 SINGAPORE 569535		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	