

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC2777T

Make : HYUNDAI

Model : IONIQ(G2)

Date: 18/12/2021

Insurance: AIG

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			<i>Ry</i> \$459.40
10	REAR BUMPER CLIPS			<i>ny</i> \$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			<i>dy</i> \$451.25
1	REAR BUMPER REINFORCEMENT			<i>?</i> \$394.80
1	REAR BUMPER LOWER CTR MOULDING			<i>X</i> \$155.00
1	ANTENNA SMARTKEY			<i>?</i> \$40.50
1	REAR BUMPER FOG LAMP			<i>?</i> \$201.50
1	LICENCE LAMP			<i>?</i> \$85.30
	SUB TOTAL			\$1,482.45
	LESS 20%			\$296.49
	DISCOUNTED TOTAL			\$1,185.96
1	REAR BUMPER RUBBER MAT			<i>X</i> \$50.00
1	REAR NUMBER PLATE WITH TRIM COVER			<i>na</i> \$55.00
1	REAR BUMPER REVERSE SENSOR			<i>m</i> \$180.00
				\$235.00
	Labour Charge			
	PANEL BEATING			<i>350</i> \$400.00
	SPRAY PAINTING CHARGE			<i>250</i> \$300.00
	CHECK ALL LIGHTING			<i>30</i> \$60.00
	REMOVE/REFIX REVERSE SENSOR			<i>30</i> \$80.00
	TOTAL LABOUR			\$840.00
	ESTIMATE TOTAL			\$2,260.96

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanfah 97415747
'wp' 20/12/21 @ 525
off leaving new parts
2 days
Tanfah @ 11/12/21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 18.12.2021 10:47

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4153433

JC NO 305498351

STOMER

/MS COMFORT TRANSPORTATION PTE LTD

STOMER NO. 7010045

DRESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

COUNT CARD NO.

REGN NO.:

SHC2777T

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

DATE/TIME IN 17.12.2021 13:35

YR OF MANU

28.09.2021

TARGET DATE

CHASSIS CODE

KMHC851CVLU184017

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 17.12.2021

ATURE: 3P 17.12.2021

S/NO

LABOR CODE

DESCRIPTION



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgment Slip

Exit Pass

No.: SHC2777T

YY

Vehicle No.:

SHC2777T

of Service Advisor

Signature/Date

Name of Service Advisor

Date

eturned to Service Reception upon collection

To be kept by Security Guard