,r.·	Olara	,
ASS. REC. BY:	Stere.	
	,	

REF: CS/EG121012844/EVF3

	ASS	GNMENT
From:	Date:	Veh No: SKU 8870 Vr Regn: 16 11), 10
Estimated Cost:		Type: M.Car) M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD TP WS ITP RES	OD RES / EVA / INV / MY	Truck / Trailer or
To Inspect Vehicle No:		Make: Mercedis - Benz EJOO c.o. 1796
at Workshop m/s		Colour Black A/C: Insured / Std / NI / NA
of	,	Sp.Reading T/Radio: Insured / Std / NI / NA
lanuari.		Eng/No:
Policy No.		C/NO: WDD 217048 2A 189569
		Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured:	Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)		Brake: Interder / Jammed / Leaked / Burnt or
Make of Veh:		Modl: NII / SRIM / STD A/RIM or
Bal, or Market Value: IDAC Accident Rport: GIA / PR Seen: Est. Repairs: Lum Sum: CA / REV / REI Date:	Consistent?: Yes or No Consistent?: Yes or No days Res.: Yes or No % 3 Val.: Yes or No	Tyre Size: F: 775/55 R16 R: 1/ BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI / TOYO / YOKO or Front Rear R/Bal. 5 mm L/Bal. 5 mm L/Bal. 5 mm L/Bal. 5 mm D.O.A. 77 / 1/1 D.O.I. 21 / 1/2 Survey held at Wah Hory Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collision.
NV	-41,109	
Deletime Ele Pere le?	T. Broll Banort	Days Of Repair:
Date/Time, File Pass to?	: Prell. Report	Resurvey No. of Trip: Survey Fee:
1) Date/Time, File Return to		Transportation:
2)	Add Fe	96: : Site Insp (\$)_s+RsSi
4	_	: Interview (\$) Photos
Report Format:	· .	: Tech. Invs (\$) Others
Lump Sum / I.B.	1: (\$: Weekend (\$)
		TOTAL

Steve CLKK) 21/12/21, 12.30pm

Wah Hong Motors & Credit Pte Ltd



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

		, , ,	. 17	1645
Our Ref	:		, ,,	7
Vehicle No.	: SKU8870L			•
Make & Model	MERCEDES	RENZ F200 C	GLA	

Page No. 1

ידע	DESCRIPTION	CONDITION	REPAIRER'S	SURVEYOR'S
YTY		CONDITION	ESTIMATE(S\$)	ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Bonnet / 00		2555.53	
1	Bonnet insulator / CRM	· _ L	296.69	
2	Bonnet hinge LH/RH @2*\$163 / 67		326.00	
2	Bonnet actuator LH/RH @2*\$412 / JR		824.00	
2	Bonnet damper LH/RH @2*\$122 / ()T	14.0	244.00	
1	Bonnet side lock LH/RH @2*\$76 / 61		152.00	
2	Bonnet side catch LH/RH @2*\$36 / GT		72.00	
1	Bonnet center hook / CR		82.00	
2	Bonnet side stopper LH/RH @2*\$35 / DC		70.00	
1	Bonnet inner rubber seal / TM		28.00	
1	Bonnet logo badge / //		102.00	
1	Center grille / MI		696.00	
1	Center grille logo badge / MIS		47.00	
1	Center grille logo badge bracket / MI		8.00	
1	Center grille inner center top bracket / MIS		29.00	
2	Front fender LH/RH / BR M		1104.00	
2	Front fender emblem "blue efficiency" LH/RH @2*\$74	- nec	148.00	
1	Front fender shield front portion LH - TN		212.00	
1	Front bumper / MI		1398.00	
2	Front bumper side retainer LH/RH @2*\$24 / MIS		48.00	
1	Front bumper lower grille / MIS		81.00	
1	Car plate base garnish / MIS		200.00	
1	Front bumper towing cover / MIS		67.00	
Æ	Front reverse sensor 6pcs * \$290 / MIS		1740.00	
1	Front reverse sensor cable / MIS	1 1	262.00	
2	Headlamp bracket LH/RH @2*\$81 /		162.00	
1	Front bumper center bracket / M)		91.00	
1	Front bumper center sponge / M[(119.00	
2	Front bumper side sponge LH/RH @2*\$74 / M/S		148.00	
2	Fog lamp cover LH/RH @2*\$45 / MI(90.00	
4	Fog lamp cover outer chrome inner & outer LH/RH @4*	\$25 MI	100.00	
2			280.00	
2	Fog lamp inner LH/RH @2*\$140 / M() Fog lamp outer LH/RH @2*\$258 / M)		516.00	
1			282.00	
			589.00	
1	Front reinforcement / 00 Front reinforcement side bracket beam LH/RH @2*\$31		632.00	

Air flow senser / BR

		Total Parts:	32420.60	1
	SI	Items Total:	465.00	
L			50.00	30
	Gearbox fluid / MC		80.00	
	Headamp light bulbs LH / BR		50.00	20 30
	Coolant / NC		35.00 50.00	
	Bonnet insulator clips / MC		30.00	20
	Radiator top garnish clips / //C		35.00	20
	Engine lower cover clips / nlc		35.00	20
	Front bumper lower cover clips / //		30.00	20
	Center Grille Clips / N(50.00	20
	Front Fender shield Clips / ne		35.00	30
	Front Bumper Clips / NC		35.00	30
,	Front Car plate with holder / MI			20
	SPECIAL NETT ITEMS		01000.00	
		Total:	31955.60	and the second second
	- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Part Items	-10% -3550.62	A Section of the Control of the Cont
			35506.22	
1	Chassis member LH/RH (Repair refer to labor) & R		0.00	
1	cross member		2613.00	
1	Rack end LH 1		191.00	
1	Tie rod end LH 1	the will be filled	181.00	100
1	Drive shaft LH		3196.00	
1	Front knuckle bearing LH		781.00	
1	Front knuckle arm LH		1335.00	Arthur Control
1	Front stabilise link LH		110.00	
١	Front control arm LH		559.00	
1	Front lower arm LH ?		542.00	
	Front absorber mounting LH ?		353.00	
	Front absorber LH ?	de la la	909.00	1.
	Radiator top garnish / MIS		131.00	1
ŀ	Headlamp LH/RH @2*\$1152 / JR	1	2304.00	
ŀ	Lighting wiring harness / BR	+	1342.00	
1	Engine lower cover / OR		156.00	
1	Radiator air guide / mis	1	173.00	
1	Fan cowling assy 🔑 🎊		1583.00	
	Inter cooling pipe LH / TN	1	166.00	
۱	Inter cooling / BR		1338.00	
1	Radiator / BR		959.00	
۱	Condenser side bracket / JK		126.00	
1	Condenser _ 00		1375.00	
1	Wiper tank cap / mis		24.00	
1	Wiper tank switch 🔏		39.00	
1	Wiper motor 1		136.00	
1	Wiper tank / BC		204.00	
1	Support top panel — 00		189.00	
2	Headlamp panel LH/RH @2*\$285 / 01) Headlamp panel lower panel LH/RH @2*\$60 / 61		570.00 120.00	

W

 No illegal modification(s) is allowed
 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Sinnature:

Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref Vehicle No. **SKU8870L** Page No. 2 Make & Model **MERCEDES BENZ E200 CGI A** SURVEYOR'S REPAIRER'S S/N DESCRIPTION ESTIMATE (S\$) **ADJUSTMENT** LABOUR To remove the affected parts & fittings to commence repairs; panel beat 1 1400.00 1999 1999 & reshape the affected areas and replace the damaged parts and components To supply paint materials, expandable items & putty, respray paint on 2 1200.00 1990 parts replaced & repaired 3 60.00 To perform anti-rust treatment on affected areas 4 To carried out repair on rear chassis member LH/RH 200 300.00 Remove and refit aircon condenser, related pipes and hoses, vaccum 150.00 120 and refill aircon gas 6 300.00 150 Airbag ECU resets and programming To carried out repair on connector and wiring system at accident 7 100.00 damaged area and check for all electrical proper function 8 Remove and replace undercarriage LH 200.00 9 Remove and replace front cross member 300.00 10 500.00 Remove and refit engine to facilitate repair 11 To remove, replace and focus headlamp beam 100.00 30 To carried out replacement of front reverse sensor 100.00 30 LKK Auto Consultants hence notify Labour Total: 4710.00 the Repairer of the following To resurvey before/after spray painting **TOTAL (PARTS & LABOUR):** 37130.60 To display damaged part(s) during Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	811Z
Vehicle No.:	SKU8870L
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Dec 2021
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200 CGI A
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	27186030047324
Chassis No.:	WDD2120482A189569
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$42,682.00
Original Registration Date:	16 Nov 2010
First Registration Date:	16 Nov 2010
Transfer Count:	2
Actual ARF Paid: Intended PARF Rebate Details	\$42,682.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	31 Oct 2030
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$38,216.00
COE Rebate Amount:	\$33,891.00
Total Rebate Amount:	\$33,891.00

The information contained herein is correct as at 17 Dec 2021



IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

oblicy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident

Exact Location of Accident

Additional Location Information

Country/State of Loss

17/12/2021 17:14 (SGT)

17/12/2021 12:40 (SGT)

Near Sungei Tengah Rd, Singapore

SUNGEI TENGAH RD TOWARDS BRICKLAND RD

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SKU8870L

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner

NRIC No

Email Address Mobile Phone No

Alternative Phone No

ER KUAN YI WILSON

SXXXX811Z

WIL_BTOP@HOTMAIL.COM

(Phone) +65-96808929

+65-96808929

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

Transmission

CC

Mercedes

E200

Private use

No - Claiming third party

Private car

Auto

1796

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy

Policy Number

Cover Note Number

Lonpac Insurance Bhd Comprehensive

Z21VP05030182

DRIVER

Name of Driver

NRIC No

ER KUAN YI WILSON SXXXX811Z

Accident report SW0C21CH0001

Page 1 of 16

30/03/1956 Date Of Birth Indoor Occupation 25/04/1977 **Date Of Driving Pass** 44 YEARS AND 8 MONTHS **Driving experience** Male Gender (Phone) +65-96808929 Mobile Number +65-96808929 Alt. Phone Number WIL_BTOP@HOTMAIL.COM **Email Address** BLK 210 BUKIT BATOK ST 21 Address #08-218 Address complement 650210 Postcode Yes Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Cross Junction
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	TAN SEOK CHENG	
Gender	Female	

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Jurong Division Headquarters
Police Station Phone No	(Phone) +65-18007910000
Alt. Police Station Phone No	(Fax) +65-68965647
Police Station Address	No. 2 Jurong West Avenue 5 Singapore 649482
Was notice of intended Prosecution given?	No
If yes, against whom?	

CIRCUMSTANCES OF ACCIDENT


PLEASE REFER TO THE POLICE REPORT (J/20211217/7084) & SKETCH PLAN FOR ACCIDENT DETAIL.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	SD CARD TAKEN BY TR
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SCG31M



Page 2 of 16

Vehicle Manufacturer	Toyota
Vehicle Model	Previa
Vehicle Variant	•
Vehicle Colour	•
Vehicle Category	Private car
Name of Driver	
Contact Number	
Address	
Address complement	
Postcode	
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident	•
No. Of Passenger (Including Driver)	

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	
Gender	-
Phone No	
Address	
Address Complement	•
Post Code	-
Approximate Age Years Old	4
Injuries Sustained	
Injured person in which vehicle?	SKU8870L
Were seat belts worn?	2
Was this injured conveyed to hospital by ambulance?	

SKETCH PLAN

IMPORTANT NOTICE


- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the recort being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose andier process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any refevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Please	efer to police report no. 1/20211717/7084	
-		
-		-

		-
		-
-		-
	**************************************	_
		-
		_
		-
		_
		-
-		- Page
_		
-		
-		
	All Commences and Commences an	
_		
		_

Declaration

IWe declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel





1 of 3

Report No. J/20211217/7084

POLICE REPORT (NP299)

Police Station Of Origin Jurong Division HQ 2 Jurong West Avenue 5 SINGAPORE 649482 Tel No:1800-7910000

Vide Rep	ort No.	A state of the sta	Station Diary No
Address 210 BUKIT BATOK STREET 21 #08-218 SINGAPORE			
Contact No. Home/Office: Mobile: 96808929 Email Address			
			Sex
Language			
Location Of Incident 210 BUKIT BATOK STREET 21 #08-218 SINGAPORE 650210			
	Address 210 BUKI 650210 Contact N Home/Off Email Add wil btop@ Sex Female Language English Location (210 BUKI	210 BUKIT BATOK 650210 Contact No. Home/Office: Email Address wil btop@hotmail.c Sex Age Female 48 Language English Location Of Incident 210 BUKIT BATOK	Address 210 BUKIT BATOK STREET 21 #08-650210 Contact No. Home/Office: Mobile: 96808929 Email Address wil btop@hotmail.com Sex Age Date of Birth Female 48 11/02/1973 Language English Location Of Incident 210 BUKIT BATOK STREET 21 #08-2

On 17/12/2021 at about 12:40pm, I was driving my vehicle (A) SKU8870L along Sungei Tengah Rd towards Brickland Rd. While I approach the cross junction traffic light, I slowed down and proceed with caution. Beside the lanes at the moment, there was a private bus at the middle lane and a lorry at the extreme right lane.

The traffic light was green at the moment, it was in my favor to drive ahead. Suddenly vehicle (B)

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.	
Signature Of Interpreter: Not applicable	Date/Time: 17/12/2021 16:10	
Officer In-Charge Of Case:	Classification Of Case:	





2 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20211217/7084

SCG31M came dashing in front of me which I believe that he was beating the red traffic light from his direction of way.

I applied emergency braked and due to the the short distance, My vehicle collided with vehicle (B) SCG31M. I stopped my vehicle immediately to check if my wife and I were injured at the point of accident. We did not suffer any major injury at the moment. So I proceed to check vehicle (B) SCG31M driver if he was fine too before dialing 995 for help. After speaking with the driver of vehicle (B) SCG31M, he seems no physical injury due to the accident collision cause by himself. So I dialed 999 to seek assist from the police officer on the phone.

Around 12 minutes later, SCDF arrived on site and check on us follow by the Traffic Police Officer who then took down our particular and collected our dashcam memory card for investigation.

Victim				
Person Name	TAN SEOK CHENG			
ID Type	NRIC NO	ID No	S7306258F	
Gender	Female	Age	48	
Race	Chinese	Language	English	
Occupation	Retiree	Address	210 BUKIT BATOK STREET 21 #08-218 SINGAPORE 650210	
Mobile No	96808929	Is Informant A Victim?	Yes	

Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.		
Date/Time: 17/12/2021 16:10		
Classification Of Case:		