



Service Request Details

Claim

S1M03OPE

Reference

CS3/ASM21012866/y3 

Loss Date

17 December 2021

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

17 Dec 2021 9:12:56 PM

Request Date

20 December 2021

Due Date

27 December 2021

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

[Decline Work](#)

Vehicle Information

Incident Vehicle Registration #
SLR9875X

Make
TPVD

Model
HONDA

Service Address

, , ,

Primary Contact/Insured

GOH JUN WEI, IVAN
APT BLK 658A PUNGGOL EAST, #16-707, 821658, Singapore
90262792
goh.junwei92@gmail.com

Claim Handler

HO Winnie

winnie.ho@axa.com.sg

Additional Instructions

Messages1

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

| TYPE | |
|------|------------------|
| SENT | 20/12/21 5:26 PM |



BODY

Dear Winnie, Thank you for the assignment. Repaire...

