


PRS

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP ☒ N/S / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s YAP MOTOR
 of _____
 Insured: _____
 Policy No: _____
 Claims No: S1M03OPE
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$75k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLR9875X Yr Regn: 31 Aug 2017
 Type ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: HONDA / FREED 1.5G c.c. 1496
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 240841 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: GB71021215
 Gen. Cond ☒ Good / Fair / Poor / Burnt
 Steering: ☒ Inorder / Jammed / Leaked / Burnt or
 Brake: ☒ Inorder / Jammed / Leaked / Burnt or
 Modi: Nil ☒ S/Rim / STD A/Rim or
 Tyre Size: F: 185/55R16
 R: 185/55R16

BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIC OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	21-12-2021

Survey held at W/S 11:15

Des. of Damages: Frt / ☒ Rea / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$2000 - \$3000
31/12/21	Simon comment range of COR: \$3000-4000
	Dismantle resurvey: 22/12/2021; After paint: 28/12/2021
21/01/21@9.38am	revised to Winnie Ho via Smart Claims.
21/01/21	Submit PRS.

Date/Time, File Pass to? ☐ : Preli. Report

1) 21/01 Typist ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : A/Weekend (\$

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Other:

TOTAL

Report Filed: SMART CLAIMS - PRS

Long Quid/MPB/