

INSPECTION CHECKLIST

Reference no: CS5/TP21012867/Cq

Section A: Vehicle Check


Applicant	VENTURE CARS PTE LTD
Date of Inspection	22/12/2021
Time of Inspection	12:30 HRS
Vehicle Make	HONDA
Vehicle Model	FIT 1.3 HOME
Vehicle Model Code	6BA-GR1
Engine Number	L13B1607240
Chassis Number	GR11105568
Motor Number (if any)	-
Odometer Reading	12 KM

Wheels	
Front Tyre Size	185/60R15
Rear Tyre Size	185/60R15

Lighting	Yes	No	Remarks
Auto Levelling System		X	
Front Fog Lamp		X	
Rear Fog Lamp		X	
Type of Low Beam	☐ Halogen	☒ LED	☐ HID
Type of High Beam	☐ Halogen	☒ LED	☐ HID

Others	Yes	No	Remarks
Sunroof / Moonroof (if any)		X	
Transmission Type	☐ Manual	☒ Automatic	

Vehicle Identification (VIN) Chassis Plate




Chassis Number Stamping



Engine Number Stamping



Front View



Rear View



Right View



Left View



Engine Compartment



Front Tyre Size




Rear Tyre Size



Instrument Panel



Exhaust System



Exhaust System



Exhaust System



Speedometer



Odometer



Vehicle Light Transmittance (VLT)


Windscreen VLT Reading: 84% (front)



Windscreen VLT Reading: 33% (rear)




Front Windows VLT Reading: 77% (left)



Front Windows VLT Reading: 77% (right)



Rear Windows VLT Reading: 29% (left)




Rear Windows VLT Reading: 29% (right)




Front Quarter Glass VLT Reading: 77 % (Left)



Front Quarter Glass VLT Reading: 77% (Right)



Rear Quarter Glass VLT Reading: 32% (Left)



Rear Quarter Glass VLT Reading: 32% (Right)



Section B: Observation**Section C: Undertaking by Authorised Inspectors**

We, hereby, verify that we have checked the above-mentioned vehicle on 22/12/21 (date)
and correctly recorded the technical information on this form.

1) Inspector's Name & Signature: Ho Leong Chuan

(with company endorsement)



2) Inspector's Name & Signature: K.K.Lau

MSc,B.ENG(HONS),PE(USA)

(with company endorsement)

