ASS. REC. BY: STEVE REF. CS/10	C211017884/E142
	ASSIGNMENT
From: Date:	Veh No: SMK 5332Y Yr Regn: Apr / 2019
Estimated Cost:	Type: (M.Car) M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD TPI WS ITP RES I OD RES / EVA / INV / MY	Truck / Trailer or
To Inspect Vehicle No:	Make: Hymotri Kong c.c N/A
	Colour Grey A/C: Insured / Std / NI / NA
at Workshop m/s	Sp.Reading 169713 T/Radio: Insured / Std / NI / NA
of	Eng/No:
Insured:	CNO: KMHK28164K4024579
Policy No.	Gen. Cond: Good / Fair / Poor / Burnt
Claims No.	Steering: Inorder / Jammed / Leaked / Burnt or
Sum Insured: Excess:	Brake: Ingree / Jammed / Leaked / Burnt or
(Client's Record)	Modi: NII / S/Rim / STD A/Rim or
Make of Veh:	Tyre Size: F: 215/55R17
(Policy Condition)	R: // O/S BS / DUN / EXNOVA / GY / FS / LIZA MIC OHTSU / PIR / SUMI /
Remark: The veh had commenced its N/S	
repair at the time of inspection.	TOYO / YOKO or
Bal, or Market Value:	Front Rear R/Bal. 5 mm
IDAC Accident Rport: Consistent? : Yes or No	(R/Bal,) (IIII)
GIA / PR Seen: Consistent? : Yes or No	L/bal.
Est. Repairs: days Res.: Yes or No	Dana Sile
Lum Sum: % 3 Val.: Yes or No	
CA / REV / REP. / 24 HRS	Des. of Damages : Frt Rear / O/S / N/S / U/C / Rooftop or
Vehicle	The U/C / Chassis frame / Body Structure affected due to collision.
Date:Person Contacted:	The U/C / Chassis frame / Body Structure diseases
Date / Time Action / Instruction) : 10 days With repairer.
8/06/2022 Steve confirmed LS \$6,550.00 (Red \$7,563.54 ; 53%)); 10 days, with repairer.
(Ned ψ7,303.34 , 3376)	
,	
Date/Time, File Pass to? : Prell. Report	Days Of Repair: 10
Singl Banart	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2)	Add Fee: : Site Insp (\$)_s+Rssi
	: Interview (\$) Photos
Report Format: TP	: Tech. Invs (\$) Others
Limp Sum / I.B.I: (\$ \$6,550.00)	; Weekend (\$)
	(tobb