

(08/11/13) wef

ASS. REC. BY:

REF:

CS/CT121012888/Riny3

1020

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNC 5490D

at Workshop m/s

of 247, ALEXANDRA RD

Insured: GBE 7418H CTI

Policy No. DMCVSNW00021322100


Claims No. SNM21D207377/C02/TANKL

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

123K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNC 5490D

Yr Regn: 2021/001

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

VOLKSWAGEN T-CROSS R-LINE c.c. 999

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

1603

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WV 6222 UZMY 000798

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Disorder / Jammed / Leaked / Burnt or

Brake: Disorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CONTINENTAL

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

16/12/21

D.O.I.

23/12/21

Survey held at

VOLKSWAGEN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 74K

20/1/22

Rasul informed final fig \$12,080.24 (Red 9233.16, 43%)

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

21/1/22-typist

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

): S + RS, SI

) Photos

) Others

TOTAL

Report Format: Merimen

Lump Sum / I.B.I: (\$ 12,080.24)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2

Mr
WONG
JAMES CHI-HANG
471 RIVER VALLEY ROAD
#04-40
SINGAPORE 248356

Document no.
Document date 17-12-2021
Customer no. 5211055606
Customer GST-ID
Dealer 30001
Job order number 2021048017/ 1
Job order date 17-12-2021
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SNC5490D	C113KZR1	28-10-2021	WVGZZZC1ZNY000798	T-Cross R-Line 1.0 TSI 85kW DSG	10

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
9801B001	LTA BREAKSEAL (OPC PLATE)				#1	650.00	695.50
2GM827025A	Rear Trunk Lid	1	pcs.	2,521.19	#1	2,521.19	2,697.67
D 169300M2	1k Window Adhesive	2	pcs.	51.30	#1	102.60	109.78
D 00940104	All Purpose Cleaner	1	pcs.	97.65	#1	97.65	104.49
D 00920002	Primer	1	pcs.	28.52	#1	28.52	30.52
D 181802M1	Activator For Precoated W	1	pcs.	26.23	#1	26.23	28.07
D 00950025	Applicator	2	pcs.	10.47	#1	20.94	22.41
3C0853586	Grommet	8	pcs.	1.70	#1	13.60	14.55
WHT007341	Rivetted Cap Nut	6	pcs.	2.50	#1	15.00	16.05
8D0853419D	Packing Adhesive	1	pcs.	30.60	#1	30.60	32.74
N 10516801	Expanding Nut	2	pcs.	1.93	#1	3.86	4.13
2GM853687A 2ZZ	Schriftzug Chrom	1	pcs.	66.37	#1	66.37	71.02
2GM807421 GRU	NAME PLATE - T- CROSS	1	pcs.	1,084.17	#1	1,084.17	1,160.06
2GM807521B GRU	Cover For Bumper Primed	1	pcs.	242.46	#1	242.46	259.43
2GM807568A 9B9	REAR BUMPER (UPPER)	1	pcs.	190.49	#1	190.49	203.82
2GM807305	Spoiler Primed	1	pcs.	564.88	#1	564.88	604.42
2GM807251C	REAR BUMPER (CTR)	1	pcs.	93.44	#1	93.44	99.98
2GM807863A	Rear Diffusor Satin Black	1	pcs.	67.23	#1	67.23	71.94
2GM807393P	REINFORCEMENT	1	pcs.	36.31	#1	36.31	38.85
2GM807394P	Schaum-Füllstück	1	pcs.	36.31	#1	36.31	38.85
2GM807393M	BUMPER FOAM	1	pcs.	36.31	#1	36.31	38.85
2GM807394M	Attachment Strip	1	pcs.	36.31	#1	36.31	38.85
WHT004694	BUMPER CTR BRACKET	1	pcs.	1.84	#1	3.68	3.94
2GM919491A	Führungsprofil	2	pcs.	11.53	#1	23.06	24.67
2GM919491	LHR BUMPER BRACKET (UPPER)	1	pcs.	11.53	#1	11.53	12.34
2GM919492	Führungsprofil	1	pcs.	11.53	#1	11.53	12.34
2GM919398 GRU	RHR BUMPER BRACKET (UPPER)	1	pcs.	11.53	#1	11.53	12.34
2GM919397 GRU	Guide Piece	1	pcs.	13.15	#1	13.15	14.07
D 180KU2A1	LHR BUMPER BRACKET (SIDE)	1	pcs.	13.15	#1	13.15	14.07
D 822150A1	RHR BUMPER BRACKET (SIDE)	1	pcs.	81.39	#1	81.39	87.09
	Expanding Nut	2	pcs.	65.42	#1	65.42	70.00
	Sensor Bracket	2	pcs.				
	Sensor Bracket	1	pcs.				
	Sensor Bracket	1	pcs.				
	Sensor Bracket	1	pcs.				
	Sensor Bracket Primed	1	pcs.				
	Sensor Bracket Primed	1	pcs.				
	2k-Plastic Adhesive	1	pcs.				
	Bonding Agent For Plastic	1	pcs.				

SWAGEN CENTRE SINGAPORE

Landra Road
ore 159934
eg. No.: 199101494Z
No.: M200985052



Quotation

Non binding - Preview

Mr
WONG
JAMES CHI-HANG
471 RIVER VALLEY ROAD
#04-40
SINGAPORE 248356

Page 2/2
Document no.
Document date 17-12-2021
Customer no. 5211055606
Customer GST-ID
Dealer 30001
Job order number 2021048017/ 1
Job order date 17-12-2021
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SNC5490D	C113KZR1	28-10-2021	WVGZZC1ZNY000798	T-Cross R-Line 1.0 I TSI 85kW DSG	10

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
2GM945701A	Reflector ? LH	1	pcs.	75.29	#1	75.29	80.56
	LABOUR FRT	2	pcs.	840.00	#1	1,680.00	1,797.60
	SPRAY PAINT FRT	2	pcs.	800.00	#1	1,600.00	1,712.00
	LABOUR REAR	5	pcs.	840.00	#1	4,200.00	4,494.00
	SPRAY PAINT REAR	5	pcs.	800.00	#1	4,000.00	4,280.00
	R&R REAR W/SCREEN	1	pcs.	840.00	#1	840.00	898.80
	TRANSFER BOOT LID MECHANISM	1	pcs.	840.00	#1	840.00	898.80
	REAR WATER LEAK TEST	1	pcs.	150.00	#1	150.00	160.50
	FRT NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60
	REAR NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60
	CHINA TAIPIING DIRECT SETTLEMENT DOA: 16/12/2021 TP VEH: GBE7418H SURVEY BY:						

Quotation valid till 24-12-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	1,410.00	19,082.67	7%	1,434.49	20,492.67	21,927.16
Total	1,410.00	19,082.67		1,434.49	20,492.67	21,927.16

Customer

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

—VISIT OUR WEBSITE: aftersales.volkswagen.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

Rasul
Hp 90010068

7 days

23/12/21 @ 0930

Service Advisor

Resurvey before paint



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	17/12/2021 10:58 (SGT)
Date of Accident	16/12/2021 19:17 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	CROSS JUNCTION VICTORIA ST & MIDDLE RD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNC5490D
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	WONG JAMES CHI-HANG
NRIC No	SXXXX102D
Email Address	wong25@gmail.com
Mobile Phone No	(Phone) +65-96308092
Alternative Phone No	+65-96308092

VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	T-Cross
Variant	T-Cross R-Line 1.0 I TSI 85kW DSG
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1000

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	VPA/P2456808
Cover Note Number	146219

DRIVER

Name of Driver	WONG JAMES CHI-HANG
NRIC No	SXXXX102D



Date Of Birth	25/06/1975
Occupation	Indoor
Date Of Driving Pass	26/12/2019
Driving experience	2 YEARS
Gender	Male
Mobile Number	(Phone) +65-96308092
Alt. Phone Number	+65-96308092
Email Address	wong25@gmail.com
Address	471 RIVER VALLEY ROAD
Address complement	#04-40
Postcode	248356
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	PUT JOSEPHINE
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE7418H
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver	MR CHANG
Contact Number	(Phone) +65-96862440
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLX8574P
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	MR CHAN
Contact Number	(Phone) +65-90050606
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Middle Road.

Victoria St.

1 → SLX 8574P
2 → SNC 5490D
3 → GBE 74121+

Describe Circumstances of the Accident

Accident took place at around 7:15pm on Thu 16th December

Location - Victoria at Middle Road intersection

- My car was ^{stationary} at the stop light waiting to make a right turn.
- It was hit from behind by the grey van. My car has one passenger at the time (wife)
- The impact moved the car forward which resulted in a light contact with the car in front of us.
- ~~The~~ My car's rear-end was damaged as a result. The car in front of me appears to have suffered minor damage to the rear bumper (hole punctured)
- The driving condition was normal (no rain, clear visibility)
- The van driver (Mr. CHANG) of (Plate # GBE 7418H) was ~~responsive~~ responsive & offered to settle internally
- The driver ~~for~~ for the car in front (Mr. Chan) also stopped ~~by~~ to assess the situation.


Contact #s:

CHANG (Van behind) - 9686 2440

CHAN (Toyota Corolla in front) - 9005 0606

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date &
Time
2021.12.17
10am

Driver's Signature (if driver is not the policyholder) / Date
& Time

 11/12/2021
Witnessed by Reporting Centre
Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	102D
Vehicle No.:	SNC5490D
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Dec 2021
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	T-CROSS R-LINE
Primary Colour:	White
Manufacturing Year:	2021
Engine No.:	DKJ113832
Chassis No.:	WVGZZZC1ZNY000798
Maximum Power Output:	85.0kW (113 bhp)
Open Market Value:	\$22,449.00
Original Registration Date:	28 Oct 2021
First Registration Date:	28 Oct 2021
Transfer Count:	0
Actual ARF Paid:	\$23,429.00
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Oct 2031
PARF Rebate Amount:	\$17,571.00
COE Expiry Date:	27 Oct 2031
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,000.00
COE Rebate Amount:	\$30,508.00
Total Rebate Amount:	\$48,079.00

The information contained herein is correct as at 24 Dec 2021

OK

Volkswagen T-Cross 1.0A TSI R-Line

Overview

Financial

Accessories

Similar

Research

Photos

Map



PREMIUM
PREOWNED

Price **\$119,999**

Depreciation \$11,390 /yr
[View models with similar depre](#)

Reg Date 29-Jun-2021
(9yrs 6mths 4days COE left)

Mileage 7,500 km

Manufactured  2020

Road Tax  \$392 /yr

Transmission Auto

Dereg Value  \$62,994 as of today ([change](#))

OMV  \$22,373

COE  \$47,821

ARF \$23,323

Engine Cap 999 cc

Power 85.0 kW (113 bhp)

Curb Weight 1,369 kg

No. of Owners 1