

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

Our Ref	: 30049/8308	Via Fax	: Eval
Date	: 30-17-31	Your Insured	: 81em 1108 T
Time of Fax	1	Date of Acc	: 19-12-21
	AICH		

Attn: Motor Claims Department

Dear Sirs

1to

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

C81134

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

♦ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811]
◆ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305	jumanibm@cdge.com.sg
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546	Fax no. 6546 8156
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006	-
-)

If we do not hear from you within the <u>next 48 hours</u>, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President Tax Accident Repair



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Warkshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717

Date/Time: 20.12.2021 10:49

REGN NO.: SHC8113U

HYUNDAI

Page: 1

am:

ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4153553

JC NO305498358

MILEAGE

FUEL

OMER

IS

COMFORT TRANSPORTATION PTE LTD

7010045

OMER NO 383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755 (R)

(O)

(P) DUNT CARD NO.

19.12.2021 19:50 TARGET DATE

YR OF MANU.

07.11.2019

IONIQ(G3)

MAKE

CHASSIS CODE KMHC851CVLU188178

COMPLETION DATE/TIME:

E.....F


JOB DESCRIPTION

:cident Date: 19.12.2021 TURE: 3P.19.12.2021 '

NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:		
	 -	

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

10.1

SHC8113U

JU AIG

Vehicle No.:

Exit Pass

SHC8113U

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

Date: 20.12.2021 Time: 11:08:37

REPAIR ESTIMATE

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO

305498358

REGN NO MILEAGE : SHC8113U : 0000000000

MAKE

: HYUNDAI

MODEL

: IONIQ(G3)

DATE OF REGN DATE/TIME IN 07.11.2019

19.12.2021 19:50

ACCIDENT DATE

: 19.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G COVER-RR BUMPER# 1 459.40 20.00 367.52

0002 04-01-0101-0111-G BUMPER COVER CLIP REAR 10 L 22.00 20.00 17.60

0003 04-01-0104-0575-G PANEL ASSY-QUARTER OUTER 1 1,768.30 20.00 1,414.64

0004 04-01-0104-2532-G BRACKET ASSY-RR BUMPER SI 1 55.80 20.00 44.64

SUB-TOTAL : 1,844.40

JOB NATURE

0000 PB

PANEL BEATING

800.00

0001 SP

SPRAYPAINT CHARGE

600.00

0002 20-204

REMOVE/REFIX UPHOLSTERY ASST REPAIR

120.00

0003 L

REMOVE/REFIX REVERSE SENSOR

50.00

SUB-TOTAL : 1,570.00

COMFORTDELGRO ENGINEERING PTE LTD

SURVEYOR NAME & SIGNATURE

Date: 20.12.2021 Time: 11:08:37

REPAIR ESTIMATE

Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO MILEAGE

305498358 : SHC8113U : 0000000000

MAKE MODEL : HYUNDAI : IONIQ(G3)

DATE OF REGN

07.11.2019

DATE/TIME IN

: 19.12.2021 19:5

ACCIDENT DATE : 19.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,414.40

AUTHORISED: YES/NO

MVA NAME & SIGNATURE

DATE:

DATE: