



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI21012926/Ktf3n2 Date: 26/01/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGX 4897T	Veh. Inspected	SJS 7292J
Policy No.		Coverage (\$)	0.00
Claim No.	C10013000/CD	Excess (\$)	0.00
Assign From	FRAULEINE KHOO	Assign Date	21/12/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA WISH (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	ZGE200013799	Colour	METALLIC PEARL WHITE
Odometer	190339 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	HABILEAD	4 mm
L/H Front Tyre	205/55 R16	HABILEAD	4 mm
R/H Rear Tyre	205/55 R16	HABILEAD	8 mm
L/H Rear Tyre	205/55 R16	HABILEAD	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/12/2021	Inspection Date	23/12/2021
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	