

Immediate Advice

To: AXA Insurance Pte Ltd 23/12/2021

Survey Details:

Date of loss	19-Dec-21
Date of appointment	21-Dec-21
Date of survey	22-Dec-21
Location of survey	M.S. LLH CAR SERVICES & PANEL

BEATING WORKSHOP

Vehicle Details:

Claim Type:	Third Part	Third Party Claim	
Vehicle number	SJM 7026	SJM 7026T	
Make and Model	VOLKSWA	VOLKSWAGEN GOLF GTI 2.0 DS	
Date of registration	27/6/201	9	
Excess	-		
Market Value	\$	148,000.00	
Parf Rebate	\$	60,625.00	
Nett Loss	\$	87,375.00	

Repair details:

Initial Estimate	ς .	_
iiiitiai Latiiiiate	7	_

Proposed/Revised repair cost:

Parts	
Check items (estimate)	
Labour	
Total	\$ -
Lump Sum(if applicable)	

Number of days for repair	<u>5</u>



Remarks:

The estimate repair cost of the damaged vehicle is in the
region of \$4,000.00 - \$5,000.00.

Mandate:

Liability(TP)	%]
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	