ASS. Rec. By: GQ

REF: CS3/ASM21012935/Gqy3

PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / TS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s LLH CAR SERVICES & PANEL BEATING WORKSHOP

of

Insured:

Policy No.

Claims No. S1M03OVC

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**



Bal. or Market Value: $148k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJM7026T Yr Regn: 27 Jun 2019

Type M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: VOLKSWAGEN GOLF GTI 2.0 c.c 1984

Colour White A/C: Insured / Std / NI / NA

Sp.Reading 56463 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVWZZZAUZKW112961 *

Gen. Cond Good / Fair / Poor / Burnt

Steering: norder / Jammed / Leaked / Burnt or

Brake: Inorde / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40ZR18

R: 225/40ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	22-12-2021

Survey held at W/S 12PM

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	$4000 - $5000
	23/12/21@3.28pm revised to Vale Oh via Smart Claims.
23/12/21	Submit PRS.

Date/Time, File Pass to?

1) 23/12 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Insp ($)

☐ : Weekend ($)

Report Format: SMART CLAIMS - PRS

Lump Sum / UP to:

Survey Fee:	
Transportation:	
___$ + RS.___SI	
Photos	
Others	
TOTAL	