

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR INS	PECTION REPO	RT		
	AXA INSURANCE	PTE LTD	Re	ef:	CS3/ASM21012940/Gvy3e2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	Da	ate:	28/12/2021	
	ATTN: DOMINIC Y	U	Co	ode:	ASM	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 2332D	Veh. Inspected		FBR 3360Y	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S1M03OXI	Excess (\$)		0.00	
	Assign From	DOMINIC YU	Assign Date		21/12/2021	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA AEROX GDR155A	c.c		155	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	MH3SG4640LJ066939	Colour		BLACK	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	110/80-14	MAXXIS		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	140/70-14	MAXXIS		6 mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
	THE VEHICLE SUS PORTION.	STAINED DAMAGES AT THE O/S	BODY AND FRONT			
	5. General Information					
5.		Gener	ai iiiioriiiatioii			
5.	Accident Date	21/12/2021	Inspect Date / Tin	ne	22/12/2021 ( 04:00 PM )	
5.	Accident Date Survey held at	301101	Inspect Date / Tin		22/12/2021 ( 04:00 PM )	
5.		21/12/2021	Inspect Date / Tin		22/12/2021 ( 04:00 PM )	
5. 5a.	Survey held at Repairer	21/12/2021  149 SHUN LI IND PARK KAKI B A-TEC AUTOMOTIVE PTE LTD	Inspect Date / Tim UKIT AVE 1 S(416009) Remarks	9)	· · · · · ·	
	A) THE INSPECTION OF THE REPAIRER WC) ENCLOSED PLI	21/12/2021 149 SHUN LI IND PARK KAKI B A-TEC AUTOMOTIVE PTE LTD	Inspect Date / Tim  UKIT AVE 1 S(416009)  Remarks  THOUT PREJUDICE D AT THE TIME OF INITIMATE. PHOTOGRAPHS.	BAS	IS. CTION.	
	A) THE INSPECTION OF THE REPAIRER WC) ENCLOSED PLI	21/12/2021  149 SHUN LI IND PARK KAKI B A-TEC AUTOMOTIVE PTE LTD  FON WAS CONDUCTED ON A "W STIMATE WAS NOT PRESENTE FAS TOLD TO PREPARE THE ES EASE FIND DAMAGED VEHICLE TO REPAIR COST OF THE DAMA	Inspect Date / Tim  UKIT AVE 1 S(416009)  Remarks  THOUT PREJUDICE D AT THE TIME OF INITIMATE. PHOTOGRAPHS.	BAS	IS. CTION.	

Report Ref No. CS3/ASM21012940/Gvy3e2

Inspected By

XING GUO QIANG

**Automotive Assessor** 

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.