

new (PIP)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 17.12.2021

Jumar!

Time: 11:27:14

Page: 1

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305498224
REGN NO : SHB6619X ✓
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4A)
DATE OF REGN : 20.12.2019
DATE/TIME IN : 17.12.2021 08:45
ACCIDENT DATE : 16.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2282-G	COVER REAR BUMPER%	1	458.60	25.00	343.95	Xr
0002	04-01-0302-0920-G	MLDG ASSY BODY ROCKER PAN	1	559.20	25.00	419.40	/nt
0003	04-01-0302-0596-G	PANEL SUB-ASSY RR DOOR LH	1	1,258.30	25.00	943.72	/Dt
0004	28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1	80.00	10.00	72.00	/nec
0005	28-01-0302-2017-A	FUEL TANK LID (PETROL ONL	1	30.00	10.00	27.00	/nec
0006	28-01-0103-0003-A	FRT DOOR LOGO CTPL	1	75.00	10.00	67.50	X NW
0007	04-01-0302-2267-G	BUMPER PIECE	10	22.00	25.00	16.50	/nec ✓

SUB-TOTAL : 1,890.07

JOB NATURE

0000	PB	PANEL BEATING	1100.00	1050
0001	SP	SPRAYPAINT CHARGE	1100.00	1000
0002	L	TRANSFER DOOR PARTS	120.00	✓
0003	L	REMOVE/REFIX REVERSE SENSOR	50.00	20

4393.34

Thuan @ Lkhau to. lom
82235769
17/12/21 1600
P/P bkr paint photo
4 days up ✓

LKK Auto Consultants Hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: