

Our Job Ref No 305498224
Date : 21/12/2021

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6548 8150

FINALIZATION FORM

To : LKK
Attn : THEVAN
: SHB6619X

Fax :

DOA 16/12/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- FY 1767L
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$1,611.89
 - (b) Labour Charges \$2,190.00
 - Total for Part-By-Part Repair Cost \$3,801.89**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 4 working days
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature : 
Name : THEVAN
Date : 23/12/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	7.49 / 2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

VEHICLE NO. : SHB6619X

JOB CARD NO. 305498224

ACC. DATE 16/12/2021

TYPE OF CASE : NTUC

SURVEY BY : LKK – THEVAN

DATE :

SUPPLEMENTARY OF PARTS AND LABOUR COSTS			
DESCRIPTION	QTY	ESTIMATE	REMARKS
WHEEL CAP	1	\$177.70	LIST / Scr
CHECK ITEM			
LABOUR			
TOTAL:		\$177.70	JUMANI

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

KOB NO : 305498224
 REGN NO : SHB6619X
 MILEAGE : 000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(C4A)
 DATE OF REGN : 20.12.2019
 DATE/TIME IN : 17.12.2021 08.43
 ACCIDENT DATE : 16.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-0920-G	MLDG ASSY BODY ROCKER PAN	1	559.20	25.00	419.40
0002 04-01-0302-0596-G	PANEL SUB-ASSY RR DOOR LH	1	1,258.30	25.00	943.72
0003 28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1	80.00	10.00	72.00
0004 28-01-0302-2017-A	FUEL TANK LID (PETROL ONL	1	30.00	10.00	27.00
0005 03-01-0302-2137-G	CAP WHEEL^	1	177.70	25.00	133.27
0006 04-01-0302-2267-G	BUMPER PIECE	10	22.00	25.00	16.50

SUB-TOTAL : 1,611.89

JOB NATURE

0000 PB	PANEL BEATING (SHB6619X)	1050.00
0001 SP	SPRAYPAINT CHARGE	1000.00
0002 L	TRANSFER DOOR PARTS	120.00
0003 L	REMOVE/REFIX REVERSE SENSOR	20.00

SUB-TOTAL : 2,190.00

new (P/P)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 17.12.2021

Jumar!

Time: 11:27:14

Page: 1

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305498224
REGN NO : SHB6619X ✓
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4A)
DATE OF REGN : 20.12.2019
DATE/TIME IN : 17.12.2021 08:45
ACCIDENT DATE : 16.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2282-G	COVER REAR BUMPER%	1	458.60	25.00	343.95	XV
0002 04-01-0302-0920-G	MLDG ASSY BODY ROCKER PAN	1	559.20	25.00	419.40	/PT
0003 04-01-0302-0596-G	PANEL SUB-ASSY RR DOOR LH	1	1,258.30	25.00	943.72	/DT
0004 28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1	80.00	10.00	72.00	/NRC
0005 28-01-0302-2017-A	FUEL TANK LID (PETROL ONL	1	30.00	10.00	27.00	/NRC
0006 28-01-0103-0003-A	FRT DOOR LOGO CTPL	1	75.00	10.00	67.50	X NV
0007 04-01-0302-2267-G	BUMPER PIECE	10	22.00	25.00	16.50	/NRC ✓

SUB-TOTAL : 1,890.07

JOB NATURE

0000 PB	PANEL BEATING	1100.00	1050 1050
0001 SP	SPRAYPAINT CHARGE	1100.00	1000
0002 L	TRANSFER DOOR PARTS	120.00	100 ✓
0003 L	REMOVE/REFIX REVERSE SENSOR	50.00	50.00 ✓

Thuan @ Lkhau to. lo m
82235769
17/12/21 1600
P/P h/c paint photo
4 days wp ✓

LKK Auto Consultancy Pte Ltd
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305498224
REGN NO : SHB6619X
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID
DATE OF REGN : 20.12.2019
DATE/TIME IN : 17.12.2021 08:4
ACCIDENT DATE : 16.12.2021

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
-------------------------	-----	-----	------------	-------	--------

TOTAL : 3,801.89

Jumar

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :