



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21012982/Atf3s2	
			Date: 27/05/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	WC 1526E	Veh. Inspected	SJT 452E
	Policy No.	D21MTGENU000010	Coverage (\$)	0.00
	Claim No.	CMTD2103787/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	22/12/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	MR053ZEE106155458	Colour	GOLD
	Odometer	166019 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
	L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	21/12/2021	Inspection Date	22/12/2021
	Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	