



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21012991/R1qf3e2	
			Date: 24/01/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHF 319E	Veh. Inspected	YP 9945J	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/11/21/2067	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	22/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	HINO XZU710R	c.c	4009	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JHHUCV3H90K027559	Colour	WHITE	
Odometer	100066 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	7.00 R16	KENDA RADIAL	7 mm	
L/H Front Tyre	7.00 R16	KENDA RADIAL	7 mm	
R/H Rear Tyre	7.00 R16 (D)	KENDA RADIAL	7/7 mm	
L/H Rear Tyre	7.00 R16 (D)	KENDA RADIAL	7/7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/11/2021	Inspection Date	23/12/2021	
Survey held at	V-TECH AUTO SERVICE No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	