

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	INDIA INTERNATIO	ONAL INSURANCE PL	Ref:	CS3/III21009199/R1vf3e2-1	
	64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date:	17/01/2022	
			Code:	III2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLR 4689A	Veh. Inspected	GBG 5970G	
	Policy No.	D21MFL0000447	Coverage (\$)	0.00	
	Claim No.	MFL2021D0003833	Excess (\$)	0.00	
	Assign From	CARINE KEK PHER SER	Assign Date	22/12/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	NISSAN NV200 1.5 MT	c.c	1461	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	VSKYBAM20Z0146165	Colour	GREY	
	Odometer	75426 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	175/60 R14	ROADIAN	6 mm	
	L/H Front Tyre	175/60 R14	ROADIAN	6 mm	
	R/H Rear Tyre	175/60 R14	ROADIAN	6 mm	
	L/H Rear Tyre	175/60 R14	ROADIAN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	31/08/2021	Inspection Date	01/09/2021	
	Survey held at	K & M LEASING PTE LTD			
		51 UBI AVENUE 1 #03-18 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				