

AIG (P)P

Jumar!

COMFORT DELORO ENGINEERING PTE LTD

Date: 22.12.2021

REPAIR ESTIMATE

Time: 09:03:03

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305498717
REGN NO : SHD46995 ✓
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.10.2020
DATE/TIME IN : 21.12.2021 14:20
ACCIDENT DATE : 20.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-0578-G	COVER-FR BUMPER//	1	430.90	20.00	344.72	/Cut
0002	04-01-0104-3918-G	BRACKET-FR BUMPER SIDE RH	1	35.00	20.00	28.00	/nec
0003	04-01-0101-0111-G	BUMPER COVER CLIP REAR front	10 L	22.00	20.00	17.60	/NOC
0004	04-01-0104-2687-G	MOULDING-FRONT BUMPER CTR	1	368.50	20.00	294.80	/DIS
0005	04-01-0104-0573-G	PANEL-FENDER RH//	1	588.80	20.00	471.04	/DT
0006	04-01-0104-2686-G	MOULDING-FRONT BUMPER RH	1	93.45	20.00	74.76	/scr
0007	04-01-0104-3913-G	EMBLEM-BLUE DRIVE RH	1	26.60	20.00	21.28	/nec ✓
SUB-TOTAL :							1,252.20

JOB NATURE

0000	PB	PANEL BEATING	800.00	700
0001	SP	SPRAYPAINT CHARGE	600.00	500
0002	17-01	CHECK ALL LIGHTING	50.00	20
0003	20-00	TUFF COAT ON AFFECTED PARTS.	50.00	20 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

F: 2492.2
Repair clay 3