

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

Our Ref	: 305498111	Via Fax	: SWALL
Date	: 20-12-21	Your Insured	: SLJ 9592D
Time of Fax	ŧ	Date of Acc	: 20-12-21

Attn: Motor Claims Department

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

046995

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

Lim Kwok Eng
 Jumani Bin Masudin
 Lim Tien Siong
 Chiang Liat Choon
 Tel: 6214 8355 or HP: 9824 0811
 Tel: 6214 8315 or HP: 9635 5305
 Tel: 6214 8398 or HP: 9635 8546
 Tel: 6214 8314 or HP: 9296 6006
 Tel: 6214 8314 or HP: 9296 6006

If we do not hear from you within the <u>next 48 hours</u>, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President
Tax Accident Repair

INSURER ENQUIRY

Find insurer Vehicle reg. no.

SLJ9592D

Date of Accident

20/12/2021 🛗

Reset

% RESULT & RECEIPT

TP Insurer Enquiry					
Insurance	AIG Asia Pacific Insurance Pte				
Period of Insurance	30/12/2020 - 29/12/2021				
Requested By	Janet Lim Siang Gek (COMFOR				
Requested Date	21/12/2021 16:10				

Payment details

Request Amount: **\$\$1.87** GST Amount: **\$\$0.13**

Total Amount Due (GST Inclusive): **\$\$2**

General Insurance Association

Records Management Centre GST Registration No: **M400017735**



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

MAKE

Date/Time: 21.12.2021 16:50

REGN NO.: SHD4699S

HYUNDAI

MODEL IONIQ(G3)

YR OF MANU. 30.10.2020

SIS CODE KMHC851CVLU191613

Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717

Page: 1

am:

ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO305498717

DATE/TIME IN 12.2021 14:20

COMPLETION DATE/TIME:

TARGET DATE

..1/2.....

MILEAGE

FUEL

21

OMER COMFORT TRANSPORTATION PTE LTD 7010045

OMER NO. 383 SIN MING DRIVE Singapore SINGAPORE 575717

65508755

(O)

(R) (P)


DUNT CARD NO.

JOB DESCRIPTION

:cident Date: 20.12.2021 TURE: 3P.20.12.2021

LABOR CODE

DESCRIPTION



			-			j
KED & PASSED OUT BY:						
SERVICE ADVISOR		,		CUSTOMER'S S	SIGNATURE	
edgement Slip		Exit Pass				
o.: SHD4699S	JU AIG	Vehicle No.:	SHD4699S			

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

Date: 22.12.2021 Time: 09:03:03

REPAIR ESTIMATE

Page: 1

: 305498717 COMPANY: THIRD PARTY'S CLAIMS (CAS) JOB NO : SHD4699S **CUSTOMER:** 7010045 REGN NO : 0000000000 ADDRESS: COMFORT TRANSPORTATION PTE LTD MILEAGE

383 SIN MING DRIVE MAKE : HYUNDAI : IONIQ(G3) **SINGAPORE SINGAPORE 575717** MODEL

DATE OF REGN : 30.10.2020 DATE/TIME IN : 21.12.2021 14:20 65508755

ACCIDENT DATE 20.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0578-G COVER-FR BUMPER# 1 430.90 20.00 344.72

0002 04-01-0104-3918-G BRACKET-FR BUMPER SIDE RH 1 35.00 20.00 28.00

0003 04-01-0101-0111-G BUMPER COVER CLIP REAR 10 L 22.00 20.00 17.60

0004 04-01-0104-2687-G MOULDING-FRONT BUMPER CTR 1 368.50 20.00 294.80

0005 04-01-0104-0573-G PANEL-FENDER RH# 1 588.80 20.00 471.04

0006 04-01-0104-2686-G MOULDING-FRONT BUMPER RH 1 93.45 20.00 74.76

0007 04-01-0104-3913-G EMBLEM-BLUE DRIVE RH 1 26.60 20.00 21.28

SUB-TOTAL : 1,252.20

JOB NATURE

0000 PB	PANEL BEATING	800.00
0001 SP	SPRAYPAINT CHARGE	600.00
0002 17-01	CHECK ALL LIGHTING	50.00

TUFF COAT ON AFFECTED PARTS. 50.00 0003 20-00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 22.12.2021 Time: 09:03:03

Page: 2

REPAIR ESTIMATE

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO

: 305498717 : SHD4699S

MILEAGE MAKE

: 0000000000

MODEL

: HYUNDAI : IONIQ(G3)

DATE OF REGN : 30.10.2020 DATE/TIME IN : 21.12.2021

21.12.2021 14:2

ACCIDENT DATE : 20.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 1,500.00

TOTAL : 2,752.20

AUTHORISED: YES/NO

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE

DATE:

DATE: