

(08/11/13) wef

ASS. REC. BY: AKM

REF:

CS/CT 21013021/R1qy3

1573

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJS 9451Dat Workshop m/s VOLKSWAGENof 247, ALEXANDRA RDInsured: CTI

Policy No. _____

Claims No. SNM21D207362/C02


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: 110K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJS 9451D Yr Regn: 2019 / FEBType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Beetle 1.2 TSI c.c. 1197Colour WHITE A/C: Insured / Std / NI / NASp.Reading 36498 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WV W22216Z KM 708121Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/452R8

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 16/12/21 D.O.I. 24/12/21Survey held at VolkswagenDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 76K

26/01/22@2.56pm revised to So Chow via Merimen.

We will be advising our Principal a cost of repair of P/P \$3,580.42 /-
 with 3 days of repair, subject to their approval
 (Red \$3560, 50%)

Date/Time, File Pass to?

☐

Prell. Report

1) 26/01 Typist

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

) : S + RS, SI

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

☐ : Weekend (\$Report Format : MER-TPLump Sum / I.B.I: (\$) 3580.42

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Tax invoice

Preview

Page 1/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Mr
HO
CHUEN KIN
772 WOODLANDS DRIVE 60
#08-164
Singapore 730772

Document no.
Document date 18-12-2021
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 30001
Job order number 2021048158/ 1
Job order date 18-12-2021
Service Advisor PEARLYN CHEONG

License plate SJS9451D	Model code 5C23EZ	First registration 27-02-2019	VIN WVWZZZ16ZKM708121	Model NBS succ. BMTDESIG 77 D7F	Mileage 21
---------------------------	----------------------	----------------------------------	--------------------------	------------------------------------	---------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	480.00	513.60
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
5C5807417CBGRU	Cover For Bumper Primed	1	pcs.	1,380.42	#1	1,380.42	1,477.05
	LABOUR	3	pcs.	840.00	#1 <i>840</i>	2,520.00	2,696.40
	SPRAY PAINTING	3	pcs.	800.00	#1 <i>800</i>	2,400.00	2,568.00
	NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60
Tax Code	Labour	Material	GST %	GST		Total amount excl. GST	Total amount incl. GST
#1	760.00	6,380.42	7%	499.83		7,140.42	7,640.25
Total	760.00	6,380.42		499.83		7,140.42	7,640.25

Customer

Service Advisor

Please inspect your vehicle prior to leaving our premises; we seek your understanding that we are not able to honour claims on scratches, dents etc. after your car has left our premises.

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All fund transfer payments should be made payable to Volkswagen Group Singapore Pte Ltd; Bank Name: Deutsche Bank AG (Singapore Branch), Bank Account: 2528214002, Swift Code: DEUTSGSG. Please indicate Customer Number (eg. 521XXXXXXX), Customer Name and Invoice Number in the payments.

Until payment of all goods (parts, accessories etc.) has been made in full to and received by Volkswagen Group Singapore (VGS), the goods remain in legal possession of VGS, irrespective if they have already been installed into your vehicle. However, the warranty of the goods (where applicable) starts with the issuance of the invoice or the collection of your car, whichever is earlier.

For warranty terms and conditions please visit our website www.volkswagen.com.sg

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Tax invoice Preview

Page

2/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Mr
HO
CHUEN KIN
772 WOODLANDS DRIVE 60
#08-164
Singapore 730772

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

18-12-2021
5211001170
200208384E
30001
2021048158/ 1
18-12-2021
PEARLYN CHEONG

License plate	Model code	First registration	VIN	Model	Mileage
SJS9451D	5C23EZ	27-02-2019	WVWZZZ16ZKM708121	NBS succ. BMTDESIG 77 D7F	21

This is an authorised document. No signature is required.

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram
Hf 90010068
3 days
28/12/21 @1000
Resy before paint

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	17/12/2021 21:48 (SGT)
Date of Accident	16/12/2021 18:05 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	SLIP ROAD ENTRANCE INTO CTE FROM MACHPERSON ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS9451D
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	HO CHUEN KIN
NRIC No	S8282157J
Email Address	CKHO_CHARLES@YAHOO.COM.SG
Mobile Phone No	(Phone) +65-96665113
Alternative Phone No	+65-96665113

VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	Beetle
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1200

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5116112241-01
Cover Note Number	-

DRIVER

Name of Driver	TUNG SZE HWEE
NRIC No	S8279881A

Date Of Birth 29/11/1982
 Occupation Indoor
 Date Of Driving Pass 01/08/2009
 Driving experience 12 YEARS AND 4 MONTHS
 Gender Female
 Mobile Number (Phone) +65-96665113
 Alt. Phone Number -
 Email Address CKHO_CHARLES@YAHOO.COM.SG
 Address BLK 772 WOODLANDS DRIVE 60 #08-164
 Address complement -
 Postcode 730772
 Is the driver the policyholder? No
 If No, Relationship of the Driver with the Insured Spouse
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 1
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes
 Police Station Name Woodlands West Neighbourhood Police Centre
 Police Station Phone No (Phone) +65-18003639999
 Alt. Police Station Phone No (Fax) +65-63640997
 Police Station Address 1 Woodlands St 12 Singapore 738622
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT

ATTACHMENT(S)


Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBJ5544M
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Commercial vehicle

Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

A - SSS9451D
B - GB3SS44M



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report no:
T/20211216/2110

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

1. The report is to be used to speed up the claims process.
2. The report is to be used by the Insurer and/or the Authorised Driver.
3. The report is to be used by the Insurer and/or the Authorised Driver as possible. Any wilful misrepresentation or withholding of material information may result in the Insurer's policy liability.
4. The report and acknowledgement of your Insurer's policy liability is not an admission of policy liability on the part of the insurance company.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name
NRIC/FIN No:

17/12/2021
2030h

Michael Yuen
8099951

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	157J
Vehicle No.:	SJS9451D
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Dec 2021
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	BEETLE 1.2 TSI
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	CYV642150
Chassis No.:	WVWZZZ16ZKM708121
Maximum Power Output:	77.0kW (103 bhp)
Open Market Value:	\$19,773.00
Original Registration Date:	27 Feb 2019
First Registration Date:	27 Feb 2019
Transfer Count:	0
Actual ARF Paid:	\$19,773.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Feb 2029
PARF Rebate Amount:	\$14,829.00
COE Expiry Date:	26 Feb 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,301.00
COE Rebate Amount:	\$18,864.00
Total Rebate Amount:	\$33,693.00

The information contained herein is correct as at 24 Dec 2021

OK

Volkswagen Beetle 1.2A TSI Sunroof

Overview Financial Accessories Similar Research Photos Map

Price	\$122,800		
Depreciation ⓘ	\$13,870 /yr View models with similar depre	Reg Date	31-Jan-2020 (8yrs 1mth 6days COE left)
Mileage	22,000 km (11.6k /yr)	Manufactured ⓘ	2019
Road Tax ⓘ	\$508 /yr	Transmission	Auto
Dereg Value ⓘ	\$43,885 as of today (change)	OMV ⓘ	\$20,479
COE ⓘ	\$35,010	ARF ⓘ	\$20,671
Engine Cap	1,197 cc	Power	77.0 kW (103 bhp)
Curb Weight ⓘ	1,340 kg	No. of Owners ⓘ	1
Type of Vehicle	Hatchback		