

Kennerh

461 210130291ke
ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s Motor Edgmont
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 863k
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 06 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Mandy

Veh No: SFR 991PA Yr Regn: 11, 13
Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Jaguar XF c.c. 2179
Colour: M.P. Blue A/C: Insured / Std / NI / NA
Sp. Reading: 192900 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: SATAC 056500 U100306
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modl: NI / S/Rim / STD / RIm or _____
Tyre Size: F: _____ R: 245/45R18
BS / DUN / EXNOVA / SY / FS / LZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front: _____ Rear: _____
R/Bal. 8 mm R/Bal. 8 mm
L/Bal. 8 mm L/Bal. 8 mm
D.O.A. 18/12/21 D.O.I. 22/12/2021
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
FR O/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Fees _____

Others _____

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech Invs (\$ _____)

☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ _____)

MOTOR EDGEVANTAGE PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity #03-01/02, Singapore 575722 & GST 201534758N

+65 6453 7683 clientservices@edgevantage.com www.edgevantage.com

To:

Mr Robin Chong

SFR9919A, JAGUAR, XF 2.2 I4D AUTO ABS D/AB 2WD 4DR HID TC

Attn: Robin Chong (91896627)

87783280 mandy

Work Order

Job No. : WJ2110249

Date : 22/10/2021

Mil in (KM) : 192900

Time in : 18/12/2021 19:00

Time out : 24/12/2021 08:00

T	Job Description	Operation	Quantity	UOM	Unit Price	Amt
Essential Works						
P	Jaguar SRS airbag module XF	Actual	2.00	PCS	1,859.00	3,718.00 ✓
P	Jaguar bonnet hinge RH XF	DIY	1.00	PCS	210.00	210.00 ✓
P	Jaguar bonnet hinge LH XF	DIY	1.00	PCS	210.00	210.00 ✓
S	Jaguar front bonnet lock RH XF	DIY	1.00	PCS	310.00	310.00 ✓
S	Jaguar front bonnet lock LH XF		1.00	PCS	310.00	310.00 ?
P	Jaguar bonnet strut XF		2.00	PCS	224.00	448.00 ?
P	Jaguar front impact sensor XF	DIY	2.00	PCS	185.00	370.00 ✓
S	Jaguar headlamp assembly XF	CM	1.00	PCS	2,860.00	2,860.00 ✓
S	Jaguar front headlamp support panel XF	DIY	1.00	PCS	1,980.00	1,980.00 ✓
S	Jaguar front bumper assembly XF	DIY	1.00	PCS	2,170.00	2,170.00 ✓
P	Jaguar front bumper lower grille RH XF		1.00	PCS	273.00	273.00 ?
S	Jaguar front bumper side bracket XF	DIY	1.00	PCS	85.40	85.40 ✓
S	Jaguar front bumper tow eye cover XF	CM	1.00	PCS	73.60	73.60 ✓
S	Jaguar front bumper Lid RH XF	CM	1.00	PCS	84.90	84.90 ✓
S	To remove, install, install front bonnet LH and RH air bags modules, front both bonnet hinges, bonnet strut, bonnet locks, impact sensors, front bumper, headlamp, front support panel	108	1.00		1,200.00	1,200.00 7500
S	To putty, spray paint front bumper, both front hinges, front bonnet, front fender RH				1,600.00	1,600.00 1000
S	To download software on airbag module, check wiring, contact diagnostic using equipment tools to run through air bag (SRS) system				400.00	400.00 2500
S	Towing charges on Dolly from Upper Thomson Road to 'Workshop (Accident tow)		1.00	(Bill)	140.00	140.00 1000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Remarks:

Accident
Cash card

Hennerth
98910663

Not otherwise
L1Pry &
Penny After Peim

This is a computer generated Work Order. No Signature is required.

Subtotal 16,442.90
GST 7.0% 1,151.00
Total 17,593.90

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	043C
Vehicle Details	
Vehicle No.:	SFR9919A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 Dec 2021
Vehicle Make:	JAGUAR
Vehicle Model:	XF 2.2 I4D AUTO ABS D/AB 2WD 4DR HID TC
Primary Colour:	Grey
Manufacturing Year:	2013
Engine No.:	4032215224DT
Chassis No.:	SAJAC0565DDU00306
Maximum Power Output:	147.0 kW (197 bhp)
Open Market Value:	\$46,716.00
Original Registration Date:	19 Nov 2013
First Registration Date:	19 Nov 2013
Transfer Count:	0
Actual ARF Paid:	\$47,403.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Nov 2023
PARF Rebate Amount:	\$26,071.00
Intended COE Rebate Details	
COE Expiry Date:	18 Nov 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$84,578.00
COE Rebate Amount:	\$16,156.00
Total Rebate Amount:	\$42,227.00

The information contained herein is correct as at 20 Dec 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 20/12/2021 17:18 (SGT)
Date of Accident 18/12/2021 17:15 (SGT)
Exact Location of Accident Upper Thomson Rd, Singapore
Additional Location Information in front of Hai Lam Sua Tee Kong Toa Temple
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SFR9919A

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner Chua Soon Beng Ellen
NRIC No S0123043C
Email Address chongrobin@gmail.com
Mobile Phone No (Phone) +65-96811919
Alternative Phone No +65-91896627

VEHICLE PARTICULARS

Manufacturer Jaguar
Model Xf
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 2179

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 2100357123-08
Cover Note Number -

DRIVER

Name of Driver Melissa Anne Loh Szu Wei
NRIC No S7628074F

