

ASS. REC. BY: T. AnglinREF: CS 3/116 2103044/Tig f3


ASSIGNMENT

COE expiry: 14/12/2023

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. **8703909901SG**
Sum Insured: _____ Excess: _____
(Client's Record)
Name of VEH: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Est. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repair: 7 days Res: Yes or No
Lump Sum: _____ % 3 Yrs. Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

NO 614.**06/01/22 Submit DAR; 7 repair days.**

Date / Time, File Page 101

1) **06/01 Typist**

Date / Time, File Return 102

2)

Report Form 1

MER-DAR

Lump Sum / L.B.A. (P)

Veh No: SL3 4805 B Yr Regn: 15/12/2008Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

MAKE: Toyota PLA's 1398Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 109695

T/Radio: Insured / Std / NI / NA

Eng/No: _____

Chassis: _____

MRO532EE / 06/25605Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / 15 / 16 / 17 / 18 / 19 / 20 / 21 / 22 / 23 / 24 / 25 / 26 / 27 / 28 / 29 / 30 / 31 / 32 / 33 / 34 / 35 / 36 / 37 / 38 / 39 / 40 / 41 / 42 / 43 / 44 / 45 / 46 / 47 / 48 / 49 / 50 / 51 / 52 / 53 / 54 / 55 / 56 / 57 / 58 / 59 / 60 / 61 / 62 / 63 / 64 / 65 / 66 / 67 / 68 / 69 / 70 / 71 / 72 / 73 / 74 / 75 / 76 / 77 / 78 / 79 / 80 / 81 / 82 / 83 / 84 / 85 / 86 / 87 / 88 / 89 / 90 / 91 / 92 / 93 / 94 / 95 / 96 / 97 / 98 / 99 / 100

Tyre Size: F: 205/55R16R: 205/55R16BS / BUN / EX / NOVA / GY / FS / LIZA / MIC / OHTSU / PIRI / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.I.

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 27/12/21 @ 3pm

Damage held at

Yip Motor

Des. of Damages: Fnt / Rear / O/S / N/S / L/O / Rooftop or

The U/O / Chassis frame / Body Structure affected due to collision.

Days Of Repair: 7Recovery No. of Trip: 1Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Vehicle Invs (\$)

Survey Fee:

Transportation:

5 x RS. \$1

Photos

Covers

Total