

ASS. REC. BY:

REF:

Smo/ 21013661/K4 Kny3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

27/12 Workshop will email document over.

Kenneth confirmed lump sum: \$1550 and 3 days
(red, \$3155.83, 67%)

Date/Time, File Pass to?

1) 21/03/23

Date/Time, File Return to?

2)

Report Format:

tp

Lump Sum / I.B.I: (\$

1550

☐ : Prell. Report
☐ : Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐ : Site Insp (\$
☐ : Interview (\$
☐ : Tech Invs (\$
☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Veh No:

SON82126

Yr Regn:

01, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MIT

ASX

c.c

1998

Colour

Dark Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

91893

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMI-X TGA 2WI-FC09087

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

225/55 R6

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

25/11/21

D.O.I.

27/12/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.