

SF0H214J0002 / FALCON-AIR AUTO SERVICES PTE LTD [128228]  
ENTRY DATE & TIME: 19/04/2021 12:45 (SGT)  
SUBMITTED BY: Andy Esporanza  
VERSION: 1 (19/04/2021 12:45 (SGT))



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	19/04/2021 12:45 (SGT)
Date of Accident	16/04/2021 22:45 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	PIE EXIT TO BKE
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK4432K
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	CHAN ENG HUAT
NRIC No	SXXXX819H
Email Address	
Mobile Phone No	(Phone) +65-
Alternative Phone No	+65-

#### VEHICLE PARTICULARS

Manufacturer	Honda
Model	Civic
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1600

#### INSURANCE COMPANY

Name of Insurance Company	Tokio Marine Insurance Singapore Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	20-MU000857-R02
Cover Note Number	

#### DRIVER

Name of Driver	ANDY CHAN YI EN
NRIC No	SXXXX617I



Accident report SF0H214J0002

Page 1 of 12

Date Of Birth	08/07/1993
Occupation	Indoor
Date Of Driving Pass	06/10/2015
Driving experience	5 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-99999991
Alt. Phone Number	-
Email Address	-
Address	-
Address complement	-
Postcode	670533
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Child
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

AS PER SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SLL8980M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-

Accident report SF0H214J0002

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) Investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

**Sketch Plan**



Describe Circumstances of the Accident

IT WAS A HEAVY TRAFFIC. VEHICLE IN FRONT OF ME STOPPED. I ALSO STOPPED. SUDDENLY VEHICLE B (SLL 8980M) HIT THE REAR PORTION OF MY VEHICLE

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel



## PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers  
Block 779 Yishun Avenue 2 #01-1545 Singapore 760779  
Tel : 62934822 Fax : 62963283

Messrs. Chan Eng Huat  
Block 533 #22-807  
Bukit Panjang Ring Road  
Singapore 670533

Bill No. DN/TP/21/0008/EMP  
19/5/2021

		Dr.
To		
Survey Fee (S \$) :		
Photographs (S \$) :		
Transport (S \$) :		
Resurvey (S \$) :		
Site-Survey (S \$) :		
Services rendered including photographs and transport charges	(S \$)	426.00
Our reference : TP/0007/21		
Insured :		
Policy / Cert. No. :		
Your Claim No. : Third Party Claim		
Vehicle : Honda Civic (A) - SLK 4432 K		
Dollars : Four Hundred Twenty Six Only		
Checked by 	for PRIORITY SERVICES	
E. & O. E.		

**Only our official receipt will be recognised for payment made on this account**



# PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers  
Block 779 Yishun Avenue 2 #01-1545 Singapore 760779  
Tel : 62934822 Fax : 62963283

## VEHICLE INSPECTION REPORT

Report No. TP/0007/21	Date of Report	: 19 May 21
To : Chan Eng Huat	Date of Request	: 22 April 21
Block 533 #22-807	Report requested by	: Chan Eng Huat
Bukit Panjang Ring Road	Date of Accident	: 16 April 21
Singapore 670533	Date of Inspection	: 22 April 21
	Claim No.	: Third Party Claim

## PARTICULARS OF DAMAGED VEHICLE

Registration Plate No	: SLK 4432 K	Odometer Reading	: 102777 km
Make	: Honda	Carrying Capacity	: 4
Model	: Civic (A)	Radio / Cassette / CD	: Yes
Year of Manufacture	: 2017	Air-Conditioner	: Yes
Colour	: White	Wing Mirror	: Yes
Engine Capacity	: 1597 cc	Clock	: Yes
Engine No	: --	Seat Belts	: Yes
Chassis / Frame No	: MRHFC5650GT000861	Others	: Nil

## TYRE CONDITION

Front Left	: 6mm	Front Right	: 6mm
Make	: Yokohama	Make	: Yokohama
Rear Left	: 6mm	Rear Right	: 6mm
Make	: Yokohama	Make	: Yokohama
Spare	:	Road Wheels Type	: Alloy

(The above represents the approximate remaining life of tyre treads)

Jack & Tools	: Intact	Spare Tyre	: Intact
--------------	----------	------------	----------

## PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Body Work	: Good
Paint Work	: Good
Handbrake	: Serviceable
Footbrake	: Serviceable
Steering	: Serviceable
Apparent engine modification	: Nil

*This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.*

**ASSESSMENT**

---

	<b><u>Repairer's Estimate (S \$)</u></b>	<b><u>Our Recommendation (S \$)</u></b>
Spare Parts :	3,504.00	1,531.36
Labour Charges :	1,390.00	720.00
Paint Work :	1,000.00	750.00
Towing Charges :	0.00	0.00
Others :	0.00	0.00
Totals :	5,894.00	3,001.36

---

Reduction (S \$) : 3,494.00

Recommended Reserve (S \$) : 2,400.00 (Lump Sum)

Estimated Normal Period of Repairs : 4 working days

---

**CONTRIBUTIONS BY INSURED**

Excess (S \$) : N/A

Others : --

The Assignment

The survey was conducted at M/s. Empire Image Pte Ltd, No. 4, Pandan Loop, (Block 1 / Block K), Singapore 128222

Follow-up inspection has been conducted.

Point of Impact

At the rear portion.

Damages

The boot lid, boot lid outer garnish, rear bumper, rear bumper lower garnish, end panel and etc.

Other parts were also found damaged. (see schedule for details)

Adjustment / Recommendation

We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle and we list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is \$3,001.36


Conclusion

The repairer has agreed to undertake repairs at a lump sum of \$2,400.00

We now revert to you for your decision on repairs.

Very truly yours

**PRIORITY SERVICES**

  
**JIMMY S. T. LEE** AMSOE, AMIRTE, AMSAE-AUS, MSAAA  
Motor Appraiser

  
**LAWRENCE NG**  
Motor Appraiser

Encl. Photographs of the damaged vehicle taken by us during inspection.

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist. %	Our Recommendation (S \$)	Dist. %
<b>To Supply :</b>					
1pc. Boot lid	Dented/bent	704.30		531.20	20
1pc. Boot lid outer garnish	Dented/holder Cracked	109.90		109.90	20
1pc. Boot lid outer garnish CIVIC garnish	Necessary	12.00		12.00	20
1pc. Boot lid centre emblem	Necessary	13.30		13.30	20
1pc. Boot lid I-VTEC emblem	Necessary	12.00		12.00	20
1pc. Boot lid lock	Serviceable	81.20		--	20
1pc. Rear bumper	Dented	883.10		617.20	20
1set rear bumper clips	Necessary	75.00		30.00	20
1pc. Rear bumper lower garnish	Dented/cracked	39.80		39.80	20
1pc. Rear bumper LH side reverse sensor	Dented/malfunctioned	145.80		145.80	20
1pc. Rear bumper LH centre reverse sensor	Dented/malfunctioned	145.80		145.80	20
1pc. Rear bumper RH centre reverse sensor	Refit	145.80		--	20
1pc. Rear bumper RH side reverse sensor	Refit	145.80		--	20
1pc. Rear bumper LH reflector cover	Dented/cracked	33.00		8.50	20
1pc. Rear bumper LH reflector	Cracked	23.00		7.90	20
1pc. Rear bumper reinforcement	Dented	180.00		180.00	20
1pc. End panel	Dented/repair	265.70		--	20
1pc. End panel inner garnish	Refit	50.30		--	20
1pc. Rear antenna sensor	Cracked	60.80		60.80	20
1pc. LH tail lamp assy	Refit	307.40		--	20
<b>Sub-Total :-</b>		<b>3,434.00</b>		<b>1,914.20</b>	
<b>Total Discount :-</b>		<b>--</b>		<b>382.84</b>	
		<b>3,434.00</b>		<b>1,531.36</b>	
<b>Special Nett Items :-</b>					
1pc. Rear number plate	Refit	70.00		--	
<b>Total For Parts :-</b>		<b>3,504.00</b>		<b>1,531.36</b>	
<b>Labour Charges :</b>					
Labour charges to panel beating, straighten and realign all affected areas. To remove, check, reinstall and replace parts.		900.00		500.00	
Check wiring and lighting system for proper function.		70.00		30.00	

Vehicle No : SLK 4432 K Honda Civic (A)

TP/0007/21


Workshop : Empire Image Pte Ltd


Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist. %	Our Recommendation (S \$)	Dist. %
Spray anti rust chemical to repaired and replaced panels.		70.00		30.00	
Remove and reinstall rear inner garnish and trim to facilitate repairs.		250.00		120.00	
Remove, check, replace and reinstall rear bumper reverse sensors and wire harness to facilitate repairs.		100.00		40.00	
Spray Painting :					
Putty and spray repaired and replaced dy panels.		1,000.00		750.00	
<b>Grand Total :-</b>		<b>5,894.00</b>		<b>3,001.36</b>	

Surveyed By : Lawrence Ng


HONDA AUTOMOBILE(THAILAND)CO.,LTD.  
CHASSIS NO. MRHFC5650GT000861  
ENGINE NO. R16B2-1601175  
TEC G SA5 NH-788P A















































SLK 4432 K

TAX INVOICE

FA INVOICE : PDL 07466

Please quote full invoice number when making payment

FALCON-AIR

V. A. Nr: <i>Empire To claim</i>	Vehicle Reg. Nr. <i>SLK 993 F</i>	Model Type <i>Honda Vezel</i>	Co. Reg. No.: 1988-04415-W
Rates/Remarks <input type="checkbox"/> inc. GST <input type="checkbox"/> exc. GST		Rental Period	Agreed Return Date
\$ 100 Per Day	\$ Per Week	KM IN	Time/Date In: <i>1430 26 04 2021</i>
\$ Per Month	\$	KM OUT	Hour Day Mth Yr
Plus First Km Free Per	, thereafter,	KM DRVN	Time/Date Out: <i>0950 12 20 2021</i>
Chargeable at \$ Per Km			Hour Day Mth Yr

Hirer's Name *CHAN ENG HUAT*

Hirer's Address *APT BLK BUKIT PANJANG RING RD*

Reg. No. Tel. No (Res/HP/Pgr) Fax. No.

Reference Contact Tel. No. (Ofc)

Driver's Name D.O.B. *27/12/1962*

Driver's Address

Tel. No. (Res/HP/Pgr) Passport/I.C. Nr./Country *S 819H*

Driving Licence Nr. Expiry / Pass Date Issued By *20/3/1980*

Additional Driver's Name D.O.B.

Additional Driver's Address

Tel. No. (Res/HP/Pgr) Passport/I.C. Nr./Country

Driving Licence Nr. Expiry / Pass Date Issued By

Method Of Payment  Cash  Cheque/Nets  Card  Bill Co

Details of Payment	Amount \$	Date	Rec'd by
* Total Payment Received			

Hirer is responsible for the first \$ 2,000.00 excess for collision/damage to first party (i.e. Falcon-Air's) vehicle (including windscreen) and also first \$ 2,000.00 excess for collision/damage to third party's vehicle for each and every accident/damage. Vehicle to be driven in Singapore only. Prohibited to enter Malaysia by Law.

*Chan Eng Huat (S 819H)*  
Hirer's signature signifies acceptance of agreement. (Please read overleaf for additional terms and conditions).

Collision Damage Excess Reduction  Accept  Decline

Personal Accident Insurance  Accept  Decline

Rental Charge Computation Dollars Cents

Vehicle Hire *4 days - 400.00*

CDER

PAI

Delivery / Collection Fee

Petrol

Misc

Sub-Total *400.00*

Add GST @ *7* % *28*

Total Net Charges (incl. GST) *428.00*

\*Less Total Prepayment/Deposit Rec'd

Balance Amount Due/Refundable

Refund Acknowledgement  By Cash  By Credit Card/Nets

Received \$ By Hirer X

Out By In By

Check In Station Computed By

Extension 1. 2. 3.

Remarks: Vehicle Out Remarks: Vehicle In

E 1/4 1/2 3/4 F ↑ Indicate petrol level when vehicle is checked out ↓ Indicate petrol level when vehicle is returned

FA RENTAL AGREEMENT NO. : PDL 07466

FALCON-AIR RENT-A-CAR PTE LTD (a subsidiary of Falcon-Air Holdings Pte Ltd)

# EMPIRE IMAGE PTE. LTD.

No: 4 Pandan Loop (Blk K/Blk 1), Singapore 128222

Fax: 67778126 H/P: 97425441 (Kenny)

Reg. Number: 201712076N

20 May 2021

**CHAN ENG HUAT**

c/o EMPIRE IMAGE PTE LTD

Final Repair Bill for Vehicle No: SLK 4432K

Vehicle Model: Honda Civic (A)

To cost of repair lump sum as recommended by surveyor ..... \$ 2,400.00 NETT  
(Priority Services)

**SINGAPORE DOLLARS: TWO THOUSAND FOUR HUNDRED ONLY.**

*Kenny Lim*

## Enquire Vehicle Owner Details

### Enquire Vehicle Owner Details ( As At 16 Apr 2021 / 22:45:00 )

#### Vehicle Owner Details ^

Owner ID Type:

**Company**

Owner ID:

**201617200G**

Owner Name:

**GRAB RENTALS PTE. LTD.**

Registered Address Type:

**Private Residential (Condo Apt or House) / Shopping / Office Complexes**

Registered Block/House No.:

**6**

Registered Street Name:

**BATTERY ROAD**

Registered Unit No.:

**# 38 - 04**

Registered Building Name:

-

Registered Postal Code:

**049909**

#### Vehicle Insurance Details ^

Vehicle No.:

**SLL8980M**

Make Description/Model:

**MAZDA / MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT**

Insurance Company Name:

**MSIG INSURANCE (SINGAPORE) PTE LTD**

Insurance Company Name:

**INDIA INT'L INS PTE LTD**

Disclaimer message:

Your search is displaying 2 records as there is an overlap in the period covered by the insurance policies. You may wish to contact the insurance companies for more information.

Save as PDF

OK →

Print

# Enquire Vehicle's Insurance Particulars

Enquire Vehicle's Insurance Particulars ( As At 16 Apr 2021 / 22:45:00 )

## Vehicle Insurance Details ^

Vehicle No.:

**SLL8980M**

Make Description/Model:

**MAZDA / MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT**

Insurance Company Name:

**MSIG INSURANCE (SINGAPORE) PTE LTD**

Insurance Company Name:

**INDIA INT'L INS PTE LTD**

Business Transaction Reference No.:

**20210420152211176626**

**Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).**

Disclaimer message:

Your search is displaying 2 records as there is an overlap in the period covered by the insurance policies. You may wish to contact the insurance companies for more information.

Save as PDF

OK →

Print



Thank you

Phee Lay San has successfully logged out.

Your last login date and time was 20 Apr 2021, 15:21:32.

To return to ONE.MOTORING, please [click here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

**Session Transaction History**

S/No	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(\$\$)
1	Vehicle	SLL8980M	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49