LOH HENG

Accident & Insurance Claims

30 Dec 2021

China Taiping Insurance Pte Ltd

Attn.: Motor Claim Department

Re: Claim no. SJN8576K

Dear Sir/madam,

ACCIDENT INVOLVING GBG1146X AND SJN8576K ON 17 - 12-2021

We understand that you are the insurer of GBG1146X vehicle.

We are instructed by the owner of motor vehicle **SJN8576K** to write,negotiate and settle the claim on their behalf for the above mentioned accident. We therefore propose to claim from you as follows:

1.	Lump sum recommended by surveyor	\$ 9100.00
2.	Loss of useage vehicle (9 Days x \$80)	\$ 720.00
3.	LTA search	\$ 7.00

\$ 9827.00

Please advise if above claim is agreeable via direct settlement with us.

Yours faithfully,

LOH HENG

BLOCK 176 #03-08 SIN MING AUTOCARE, SIN MING DRIVE, SINGAPORE 575721 PHONE: 64532237 / 64530797 FAX: 64556384

EMAIL: lohheng0308@yahoo.com.sg

AUTHORIZE TO ACT

30 Dec 2021

The Claim Manager
China Taiping Insurance Pte Ltd

Singapore

Accident involving GBG1146X and SJN8576K on 17-12- 2021

I , ONG KENG LEONG, hereby authorize my repairers **M/S LOH HENG** of 176 Sin Ming Drive #03-08 Sin Ming Auto Care, Singapore 575721 whom I have appointed as my agent in respect of my claim.\

I further authorize to negotiate and release all proceeds of settlement monies to my repairers **M/S LOH HENG** in settlement of my claim

Signature / Date



Automotive Repair Services Accident Insurance Claims

To: China Taiping Insurance Pte Ltd

Date:

10/1/2021

Invoice No. 36906

Terms:

Vehicle No. : SJN8576K		Toyota Wish		
Description	Qty	Unit Price	Total	
To repair the above accident vehicle as per lump	4			
sum recommended by surveyor.			\$ 9	,100.00
TOTAL:			\$ 9	,100.00
	To repair the above accident vehicle as per lump sum recommended by surveyor.	To repair the above accident vehicle as per lump sum recommended by surveyor.	Description Qty Unit Price To repair the above accident vehicle as per lump sum recommended by surveyor.	Description Qty Unit Price Total To repair the above accident vehicle as per lump sum recommended by surveyor. \$ 9