

MOTOR SURVEY ASSIGNMENT

Date	24/12/2021	Our Ref No.	D21003498MFCV
Accident Date	20-12-2021	Claim Type	Third Party
Insured Vehicle	XD4289C	Third Party Vehicle	SLN3778D

Survey Location	HIN LUNG WORKSHOP Blk 1008 Bukit Merah Lane 3 #01- 20 (S) 159722	Contact Person	ANNA
Contact No.	68583000	Fax No.	64760075

Survey Type Without Prejudice
Request for TPV VF

Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person		Fax No.	68416315
Contact Number	62563561		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Encl. Accident Reports & Estimate

Cc : Workshop HIN LUNG WORKSHOP
Officer Incharge ERICWOO

Attention ANNA

IMPORTANT NOTE

Kindly submit the survey report by **email only** to surveyor@msfirstcapital.com.sg within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.