

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21013113/Gvy3e2	
	8 SHENTON WAY SINGAPORE 0688		Date:	17/01/2022		
	ATTN: LOH CYNTH	AIA		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SH 8326R	Veh. Inspected		SLZ 2950R	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S1M03OWY	Excess (\$)		0.00	
	Assign From	LOH CYNTHIA	Assign Date		24/12/2021	
2. Vehicle Particulars & Condition						
	Make & Model	MAZDA 6	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	JM6GL1071J0147031	Colour		BLUE	
	Odometer	45132 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/55 R17	BRIDGESTONE		6 mm	
	L/H Front Tyre	225/55 R17	BRIDGESTONE		6 mm	
	R/H Rear Tyre	225/55 R17	BRIDGESTONE		6 mm	
	L/H Rear Tyre	225/55 R17	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
5.	General Information					
	Accident Date	18/12/2021	Inspect Date /	Time	29/12/2021 (04:30 PM)	
	Survey held at	Survey held at MERLIN MOTOR & ENGINEERING WORKS				
		BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #03-13 AMK AUTOPOINT SINGAPORE 568047				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					
	•					

Report Ref No. CS3/ASM21013113/Gvy3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.