FAQ English (SG) ▼ Elaine Kuan ▼

Service Requests

Claim S1M03OWY

Reference CS3/ASM21013113/Gvy3e2

Loss Date 18 December 2021

Vendor Name LKK AUTO CONSULTANTS

PTE LTD (TP)


Type of Loss Third Party Vehicle Damage

Report Date 21 Dec 2021 12:12:20 PM

Request Date 24 December 2021

Due Date

Services Pre-Repair Survey



Vehicle Information

Incident SLZ2950R

Vehicle

Registration #

Make TPVD

Model MAZDA

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD 383 SIN MING DRIVE, 575717, Singapore 65551188

