

ASS. FRY:

REF: CC4/ASM 21013121/Drs³

ASSIGNMENT

From: _____ Date: _____

Estimate Cost: _____

CD / ~~RES~~ / TP RES / DD RES / EVA / INV / INV

To Inspect Vehicle No: _____

at Work to m/s _____

of _____

Insured _____

Policy No _____

Claims to _____


Sum Insured _____ Excess: _____

(Check record)

Make claim: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bel. of Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / FR Seen: _____ Consistent? : Yes or No

Est. Repair: 7 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBK 2047X Yr Regn: 2020 / Feb

Type: M. Car / M. Cycle / Bus / Van / Truck / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna CC 2982

Colour: Silver A/C: Insured / Std / RE / NA

Sp. Reading: 72491 T/Radio: Insured / Std / RE / NA

Eng/No: 1KD B020075

C/No: JT.FAT35YXOK214727

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: REI / S/Rim / STD A/Rim or

Tyre Size: F: 195 / 75 R15

R: 155 R12C (double)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SURUI /

TOYO / YOKO or

Front: Bridgestone Rear: Yokohama

R/Bal: S mm R/Bal: S/S mm

L/Bal: S mm L/Bal: S/S mm

D.O.A: 23/12/21 D.O.I: 27/12/2021

Survey held at: Atyasa Auto AMK

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rent y Rev

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time	Action/Instruction
	<u>AS AXIA SLW 6871A</u>
	<u>MV 68K</u>
	<u>VIA 17.7K</u>
	<u>HL 50.3K</u>
<u>16/02/2022</u>	<u>Income 456,800/- with 7 days of rep</u>

Date/Time, File Pass to? : Prel. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insur (\$)

: Interview (\$)

Survey Feet:

Transportation

S + RS \$

Photos