

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_ Cam Del

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: 8182K

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLZ 6898T Yr Regn: 06, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA WagonMake: Toy Will Fire c.c. 2893Colour: h. Black A/C: Insured / Std / NI / NASp. Reading: 24182 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: AG1430 0361728

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_ R: 235/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 11/12/21 D.O.I. 27/12/2021

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: \_\_\_\_\_

1)

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

Survey Fee: \_\_\_\_\_

2)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_) ☐ : S - RS \$ \_\_\_\_\_☐ : Interview (\$ \_\_\_\_\_) ☐ : Extras☐ : Tech Invs (\$ \_\_\_\_\_) ☐ : Others☐ : Weekend (\$ \_\_\_\_\_)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

**REPAIR DETAILS****Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Dec 2021)

Parts: M1-MPV TOYOTA VELLFIRE 2.5 Z G-EDITION CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SLZ6698T/27/12/2021 11:40

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

| No. | Qty | Part No. | Particulars                       | %Disc | %Depr | Amount       |    |
|-----|-----|----------|-----------------------------------|-------|-------|--------------|----|
| 1   | 1   |          | *BONNET                           | 25.00 | 0.00  | *864.00 FL   |    |
| 2   | 1   |          | *BONNET LOCK                      | 25.00 | 0.00  | *139.00 FL   | X  |
| 3   | 1   |          | *BONNET HINGE RH                  | 25.00 | 0.00  | *65.00 FL    | ✓  |
| 4   | 1   |          | *BONNET HINGE LH                  | 25.00 | 0.00  | *65.00 FL    | X  |
| 5   | 1   |          | *HEADLAMP RH                      | 25.00 | 0.00  | *9,727.00 FL | ✓  |
| 6   | 1   |          | *HEADLAMP LOWER BRACKET RH        | 25.00 | 0.00  | *378.00 FL   | 7  |
| 7   | 1   |          | *FRONT BUMPER                     | 25.00 | 0.00  | *2,332.00 FL | 11 |
| 8   | 1   |          | *FRONT BUMPER SIDE RETAINER RH    | 25.00 | 0.00  | *105.00 FL   | 11 |
| 9   | 1   |          | *FRONT BUMPER SIDE GARNISH        | 25.00 | 0.00  | *1,281.00 FL | 11 |
| 10  | 1   |          | *FRONT BUMPER CHROME TOP          | 25.00 | 0.00  | *282.00 FL   | 11 |
| 11  | 1   |          | *FRONT BUMPER SIDE GARNISH CHROME | 25.00 | 0.00  | *160.00 FL   | 11 |
| 12  | 1   |          | *FRONT BUMPER SENSOR              | 25.00 | 0.00  | *420.00 FL   | 11 |
| 13  | 1   |          | *FRONT RH FENDER                  | 25.00 | 0.00  | *1,373.00 FL | 7  |
| 14  | 1   |          | *FRONT GRILLE WITH CHROME         | 25.00 | 0.00  | *2,609.00 FL | 7  |

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) 19,800.00

- List Item Discount on L Items (S\$) 4,950.00

Total Parts (S\$) 14,850.00

ComfortDelGro Engineering Pte Ltd/SLZ6698T/27/12/2021 11:40. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Estimates on Miscellaneous Items

| Qty                        | Particulars            | Amount |
|----------------------------|------------------------|--------|
| <u>Miscellaneous Items</u> |                        |        |
| 1                          | 1 OD/TP Case (Insurer) | 11.00  |
| Sub Total (S\$)            |                        | 11.00  |

## Estimates on Labour

| No                      | Particulars                                                                                                                   | Lab.Type | Amount                   |
|-------------------------|-------------------------------------------------------------------------------------------------------------------------------|----------|--------------------------|
| <u>Labour Items</u>     |                                                                                                                               |          |                          |
| 1                       | TO KNOCK ,STRAIGHTEN AND RENEW ACCIDENT AREAS SUCH AS BONNET,FRT BUMPER,RH FRT FENDER,FRT SUPPORT PANEL ,RH HEADLAMP AND ETC. | New      | 960.00 <sup>6001</sup>   |
| 2                       | TO PUTTY,RESPRAY ACCIDENT AREAS SUCH AS BONNET FRT BUMPER FRT EH FENDER,FRT SUPPORT PANEL AND ETC                             | New      | 1,000.00 <sup>7501</sup> |
| 3                       | TO CHECK LIGHTING AND WIRING                                                                                                  | New      | 50.00 <sup>201</sup>     |
| Gross Labour Cost (S\$) |                                                                                                                               |          | 2,010.00                 |

ComfortDelGro Engineering Pte Ltd/SLZ6698T/27/12/2021 11:40. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

# ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road

Singapore 579701

Tel: 63838115 Fax: 62815767/65462533 Email: choojy@cdge.com.sg

INSURER:

India International Insurance Pte Ltd (HQ)

## PARTICULARS OF CLAIM

|                     |                                  |                       |            |
|---------------------|----------------------------------|-----------------------|------------|
| Claim Type:         | OD (OWN DAMAGE)                  | Ref. No:              |            |
| Policy No:          | D20MFL0000326-01                 | Date of Loss:         | 11/12/2021 |
| Vehicle Reg. No.:   | SLZ6698T                         | Driveable?            |            |
| Driver Age/Info:    |                                  | Party At Fault:       | UNKNOWN    |
| TP Injury Involved? | NO                               | Third Party Involved? | YES        |
| Insured/Claimant:   | COMFORTDELGRO RENT-A-CAR PTE LTD |                       |            |

|                 |                                          |                    |              |
|-----------------|------------------------------------------|--------------------|--------------|
| Make/Model:     | TOYOTA VELLFIRE, 2.5 Z G-EDITION CVT (A) | Vehicle Reg. Date: | 28/06/2021   |
| Vehicle Colour: | BLACK                                    | Chassis No:        | AGH300361728 |
| Engine No:      | 2AR2596406                               |                    |              |
| Odometer:       | 0 KM                                     |                    |              |

*Not Notified*  
*Recovery B4 pain*

|                               |          |
|-------------------------------|----------|
| Paint Type:                   |          |
| List Item Discount:           | 25.00 %  |
| Total Loss?                   | NO       |
| Est. Duration of Repair (day) | 8/4 days |

|                   |                                              |
|-------------------|----------------------------------------------|
| Present Location: | COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL) |
|-------------------|----------------------------------------------|

| COST OF CLAIMS      |  | Amount    |
|---------------------|--|-----------|
| Parts               |  | 14,850.00 |
| Miscellaneous Items |  | 11.00     |
| Labour              |  | 2,010.00  |
| Paintwork Labour    |  | 0.00      |
| Towing              |  | 0.00      |
| Gross Total (\$\$)  |  | 16,871.00 |
| + GST 7.00% (\$\$)  |  | 1,180.97  |
| Nett Amount (\$\$)  |  | 18,051.97 |

This claim is handled by: PATRICK TIA JEE KIANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 13/12/2021 18:36 (SGT)  
Date of Accident ..... 11/12/2021 18:20 (SGT)  
Exact Location of Accident ..... 10 Bayfront Ave, Singapore 018956  
Additional Location Information .....  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SLZ6698T

### INSURED/POLICYHOLDER

Is company? ..... Yes  
Name Of Registered Owner ..... COMFORTDELGRO RENT-A-CAR PTE LTD  
Company Reg No ..... 1XXXXX775H  
Email Address ..... dannyng@cdgrentacar.com.sg  
Mobile Phone No ..... (Phone) +65-98165642  
Alternative Phone No ..... (Office) +65-68820888

### VEHICLE PARTICULARS

Manufacturer ..... Toyota  
Model ..... Vellfire  
Variant .....  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... Yes  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 2493

### INSURANCE COMPANY

Name of Insurance Company ..... India International Insurance Pte Ltd  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... Yes  
Policy Number ..... D20MFL0000326\_01  
Cover Note Number ..... -

### DRIVER

Name of Driver ..... FANG TAI WAH DALE  
NRIC No ..... SXXXX632F

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time 13/12/2021 1330

Witnessed by Reporting Centre Personnel

Dahnial

Sketch Plan

