nil



MOTOR SURVEY ASSIGNMENT

**Date** 27/12/2021 **Our Ref No.** D21003528MFBP

Accident Date 23-12-2021 Claim Type Third Party

Insured Vehicle SBS6390K Third Party Vehicle SJB2217A

Survey Location KING'S AUTO REPAIR & Contact Person

SERVICE PTE LTD

BLK 176 SIN MING DRIVE #02-10 SIN MING AUTOCARE (S)

575721

**Contact No.** 64578629 **Fax No.** 64517651

Survey Type Without Prejudice

Appointed LKK AUTO CONSULTANTS PTE LTD

Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person Fax No. 68416315

Contact Number 62563561

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**Encl. Accident Reports** 

Cc: Workshop KING'S AUTO REPAIR & SERVICE PTE LTD Attention nil

Cc: TP Solicitor JUSEQUITY LAW CORPORATION TP Solicitor Fax No 65365368

Officer Incharge RACHELWU

## **IMPORTANT NOTE**

Kindly submit the survey report by **email only** to <u>surveyor@msfirstcapital.com.sg</u> within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.