

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLH 8853Tat Workshop m/s KAH MOTORof 285, ALEXANDER RDInsured: SMR

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 57K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLH 8853T Yr Regn: 2016 / NOVType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda HRV 1.5 DX CVT c.c. 1496Colour: Red A/C: Insured / Std / NI / NASp. Reading: 093634 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JHMRU18106X20141Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 20/12/21

Survey held at

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 04/01/22

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - RIKWe will be advising our Principal a cost of repair of P/P  
\$5,443.98 /- with 5 days of repair, subject to their approval

red: 3853.93;41%

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final ReportDays Of Repair: 5

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

1)

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)

) : S + RS, SI

) : Photos

) : Others

Report Format : \_\_\_\_\_



**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

<b>Customer</b>	: SMRT TAXIS PTE LTD	<b>Document No.</b>	: SQT21003932	<b>Page</b>	1
	60 WOODLANDS INDUSTRIAL	<b>Date</b>	: 22. Dec 2021		
	PARK E4	<b>Customer No.</b>	: WZS002		
	SINGAPORE 757705	<b>Svc Advisor</b>	: IVAN TEO BOON KIAT		
<b>Registration No</b>	: SLH8853T	<b>Engine No</b>	: L15B4531141		
<b>Chassis No</b>	: JHMRU1810GX201141	<b>Date   Time</b>	: 22. Dec 2021 11:43:47 AM		
<b>Model</b>	: HRV DX-SIN CVT YM 2016	<b>Surveyor Name</b>	:		
<b>Owner's Name</b>	: CHOO HUI ZHEN, ALENE	<b>Survey Date</b>	:		
<b>Ins Policy No.</b>	:	<b>Authorisation Date</b>	:		
<b>Date of Accident</b>	: 20/12/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: )						
	OWNER: CHOO HUI ZHEN ALENE						
	OWNER INSURER: TOKIO MARINE						
	ACC DATE: 20/12/2021						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: SMRT						
	TP VEH: SHF337C						
04711-T7A-N00ZZ	FACE,FR.BUMPER <i>de/</i>	1	507.10	25	380.32	26.62	406.94
71102-T7B-000	FACE FR. BUMPER LOWER <i>scr/</i>	1	374.40	25	280.80	19.66	300.46
71103-T7A-000	GRILLEFR.BUMPER <i>EX</i>	1	84.20	25	63.15	4.42	67.57
71105-T7A-000	GARNISH,R.FR.FOG LIGHT <i>?</i>	1	24.10	25	18.07	1.26	19.33
71140-T7A-000	BEAMR.FR.BUMPER UPPER <i>?</i>	1	28.10	25	21.07	1.47	22.54
71193-T7A-J00	SPACER,R.FR.BUMPER SIDE <i>rec/</i>	1	11.70	25	8.77	0.61	9.38
71198-T7A-J00	SPACER,L.FR.BUMPER SIDE <i>rec/</i>	1	11.70	25	8.77	0.61	9.38
91505-TM8-003	CLIP,BUMPER <i>rec/</i>	22	2.30	25	37.95	2.66	40.61
71130-T7A-010ZZ	BEAM COMP,FR.BUMPER <i>?</i>	1	237.80	25	178.35	12.48	190.83
60210-T7A-J00ZZ	PANEL COMP,R.FR.FENDER <i>repair</i>	1	421.10	25	315.82	22.11	337.93
74107-T7B-003	PROTECTOR,R.FR.WHEEL ARCH <i>scr/</i>	1	163.80	25	122.85	8.60	131.45
33100-T7S-E11	HEADLIGHT ASSY,R. <i>scr/</i>	1	1952.70	25	1464.52	102.52	1567.04
60400-T7A-901ZZ	BULKHEAD COMP,FR. <i>X</i>	1	463.30	25	347.47	24.32	371.79
<b>Sum Item</b>					<b>3247.91</b>	<b>227.34</b>	<b>3,475.25</b>
BOSUN	SUNDRIES	1	50.00		50.00	3.50	53.50
BML011	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	280.00		280.00	19.60	299.60
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS. <i>2650</i>	1	2600.00		2600.00	182.00	2782.00

Printed on 27/12/2021 1:54:41 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: [www.honda.com.sg](http://www.honda.com.sg)

For 24-hours Roadside Assistance, Call 98203838

## QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer** : SMRT TAXIS PTE LTD  
60 WOODLANDS INDUSTRIAL  
PARK E4  
SINGAPORE 757705  
**Registration No** : SLH8853T  
**Chassis No** : JHMRU1810GX201141  
**Model** : HRV DX-SIN CVT YM 2016  
**Owner's Name** : CHOO HUI ZHEN, ALENE  
**Ins Policy No.** :  
**Date of Accident** : 20/12/2021

**Document No.** : SQT21003932 **Page** 2  
**Date** : 22. Dec 2021  
**Customer No.** : WZS002  
**Svc Advisor** : IVAN TEO BOON KIAT  
**Engine No** : L15B4531141  
**Date | Time** : 22. Dec 2021 11:43:47 AM  
**Surveyor Name** :  
**Survey Date** :  
**Authorisation Date** :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P) @520	1	3120.00		3120.00	218.40	3338.40
			1560	Sum Labor	6050.00	423.50	6,473.50

Survey By

Date & Time

Excess

Status

Signature

Rasul - Hp 90010068

04/01/22 @ 1150

5 days  
Res before  
paint

**Total Amount** 9,297.91 650.84 9,948.75

**Total (Inclusive of GST)** 9,948.75

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	21/12/2021 12:54 (SGT)
Date of Accident	20/12/2021 00:05 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	BLK 38 LOR 5 TOA PAYOH CARPARK
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH8853T
-----------------------------	----------

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHOO HUI ZHEN ALENE
NRIC No	SXXXX036F
Email Address	ALENECHOOALENECHOO@GMAIL.COM
Mobile Phone No	(Phone) +65-97398330
Alternative Phone No	+65-97398330

### VEHICLE PARTICULARS

Manufacturer	Honda
Model	Hr-v
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1500

### INSURANCE COMPANY

Name of Insurance Company	Tokio Marine Insurance Singapore Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	MV010967
Cover Note Number	-

### DRIVER

Name of Driver	CHOO HUI ZHEN ALENE
NRIC No	SXXXX036F

Date Of Birth	25/12/1989
Occupation	Indoor
Date Of Driving Pass	10/06/2009
Driving experience	12 YEARS AND 6 MONTHS
Gender	Female
Mobile Number	(Phone) +65-97398330
Alt. Phone Number	+65-97398330
Email Address	ALENECHOOALENECHOO@GMAIL.COM
Address	BLK 38 LORONG 5 TOA PAYOH #01-491
Address complement	-
Postcode	310038
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHF337C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	-
Contact Number	(Phone) +65-96196154
Address	-
Address complement	-

First  
Capital

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that :

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Alum  
Policyholder's Signature / Date & Time  
Sketch Plan

\_\_\_\_\_  
Driver's Signature (If driver is not the policyholder) / Date & Time

J  
Witnessed by Reporting Centre Personnel




Describe Circumstances of the Accident

My vehicle was parked stationary in the car park at night.  
When I went to retrieve my vehicle, I found a note on my car.  
I called the number on the note, the person on the phone told me that  
he had knocked into my car while reversing.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &  
Time

Driver's Signature (If driver is not the policyholder) / Date  
& Time



Witnessed by Reporting Centre  
Personnel

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	036F
Vehicle No.:	SLH8853T
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jan 2022
Vehicle Make:	HONDA
Vehicle Model:	HRV 1.5 DX CVT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	L15B4531141
Chassis No.:	JHMRU1810GX201141
Maximum Power Output:	96.0kW (128 bhp)
Open Market Value:	\$21,466.00
Original Registration Date:	22 Nov 2016
First Registration Date:	22 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$17,053.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Nov 2026
PARF Rebate Amount:	\$11,937.00
COE Expiry Date:	21 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,506.00
COE Rebate Amount:	\$25,137.00
Total Rebate Amount:	\$37,074.00

The information contained herein is correct as at 04 Jan 2022

OK

# Honda HR-V 1.5A DX

Overview

Financial


Accessories

Similar

Research

Photos

Map



Insurance Agent of



Liberty Insurance



Superior Work and Drive



Insurance Agent of



Member of



Price

**\$57,800**

Depreciation ⓘ

\$10,110 /yr

[View models with similar depre](#)

Reg Date

24-Nov-2016

(4yrs 10mths 19days COE left)

Mileage

87,000 km (17k /yr)

Manufactured ⓘ

2016

Road Tax ⓘ

\$682 /yr

Transmission

Auto

Dereg Value ⓘ

\$36,654 as of today ([change](#))

OMV ⓘ

\$21,256

COE ⓘ

\$50,991

ARF ⓘ

\$16,759

Engine Cap

1,496 cc

Power

96.0 kW (128 bhp)

Curb Weight ⓘ

1,185 kg

No. of Owners

2