

MOTOR SURVEY ASSIGNMENT

Date	27/12/2021	Our Ref No.	D21003536MFCV
Accident Date	25-12-2021	Claim Type	Third Party
Insured Vehicle	GBD6373P	Third Party Vehicle	SLR8313H

Survey Location	HUI YANG MOTOR PTE LTD BLK 176 SIN MING DRIVE #04- 02 SIN MING AUTOCARE (S) 575721	Contact Person	BEL
------------------------	---	-----------------------	-----

Contact No.	64545752	Fax No.	0
--------------------	----------	----------------	---

Survey Type Without Prejudice

Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person		Fax No.	68416315
Contact Number	62563561		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Encl. Accident Reports & Estimate

Cc : Workshop	HUI YANG MOTOR PTE LTD	Attention	BEL
Officer Incharge	CHRISLIM		

IMPORTANT NOTE

Kindly submit the survey report by **email only** to surveyor@msfirstcapital.com.sg within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.