

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE I	PTE LTD		Ref:	CC4/ASM21013158/Ups3q2
	8 SHENTON WAY AXA TOWERSING			Date:	18/03/2022
	ATTN:CYNTHIA			Code:	ASM
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SH 7465D	Veh. Inspected	l	SML 1550E
	Policy No.	P2419138	Coverage (\$)		0.00
	Claim No.	S1M03PDL	Excess (\$)		0.00
	Assign From		Assign Date		27/12/2021
2. Vehicle Particulars & Condition					
	Make & Model	HONDA CITY (A)	c.c		1497
	Engine No.	HIDDEN	Year of Reg.		2019
	Chassis No.	MRHGM6670KT000268	Colour		BLUE
	Odometer	60766 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	175/65 R15	MICHELIN		6 mm
	L/H Front Tyre	175/65 R15	MICHELIN		6 mm
	R/H Rear Tyre	175/65 R15	MICHELIN		6 mm
	L/H Rear Tyre	175/65 R15	MICHELIN		6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	25/12/2021	Inspection Dat	е	27/12/2021
	Survey held at	FASTECH AUTO PTE LTD			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		4 Worki	ng Days