

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 199607196R GS1 Reg. No. 19-9607196-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	Ī	Ref:	CS/AGI21013160/Avf3n2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	1	Date:	13/05/2022	
			(Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLT 3656R	Veh. Inspected		SMA 4628D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10013074/CD	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		27/12/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI ATTRAGE	c.c		1193	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	MMBSTA13AJH001625	Colour		BLUE	
	Odometer	246287 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	185/55 R15	FALKEN		6 mm	
	L/H Front Tyre	185/55 R15	FALKEN		6 mm	
	R/H Rear Tyre	185/55 R15	FALKEN		6 mm	
	L/H Rear Tyre	185/55 R15	FALKEN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	24/12/2021	Inspection Date)	28/12/2021	
	Survey held at	HUA MENG SPRAY PAINTING	WORKSHOP			
		1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

12 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: