



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG			Ref: CC4/ASM21013182/Apa3q2 Date: 19/10/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMA 5280R	Veh. Inspected	GBK 3611K
	Policy No.	GA540548	Coverage (\$)	0.00
	Claim No.	S1M03P7U	Excess (\$)	0.00
	Assign From		Assign Date	27/12/2021
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN NV200	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	JN1YAAM20Z0000522	Colour	WHITE
	Odometer	61027 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	175/70 R14	YOKOHAMA	6 mm
	L/H Front Tyre	175/70 R14	YOKOHAMA	6 mm
	R/H Rear Tyre	175/70 R14	YOKOHAMA	6 mm
	L/H Rear Tyre	175/70 R14	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/12/2021	Inspection Date	28/12/2021
	Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	