

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: **27-Dec-21**

INSURANCE: **AIG ASIA**

MODEL: **Hyundai Ioniq**

MVA: **LIM T S**

VEHICLE NO.: **SHB6353L**

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$430.90 <i>Ky</i>
	Front Bumper Side Bracket RH	1		\$35.00 <i>?</i>
	Front Bumper Clips	10	\$2.20	\$22.00 <i>ker</i>
	Front Fender RH	1		\$588.80 <i>by</i>
	Front Fender Shield RH	1		\$164.70 <i>?</i>
	Front Fender Blue-Drive RH	1		\$26.60 <i>ne</i>
	Front Wheel Cap RH	1		\$346.40 <i>ant</i>
	Front Bumper Grille RH	1		\$93.45 <i>X</i>
	Headlamp RH	1		\$1,993.65 <i>X</i>
	SUB TOTAL			\$3,701.50
	LESS 20%			\$740.30
	DISCOUNTED TOTAL			\$2,961.20
	Frnt Fender Adv.Sticker RH	1		\$100.00 <i>ndy</i>
	Frnt Door Adv.Sticker RH	1		\$100.00 <i>ndy</i>
	Front Door ComfortDelGro RH	1		\$75.00 <i>ndy</i>
	NETT TOTAL			\$275.00
	TOTAL SPARE PARTS			\$3,236.20
	Labour Charge			
	Panel Beating			\$800.00 <i>525</i>
	Spray Painting			\$900.00 <i>750</i>
	Check Wirings			\$40.00 <i>*</i>
	Tuff Kote			\$40.00 <i>30</i>
	Wheel Alignment			\$120.00 <i>80</i>
	TOTAL LABOUR			\$1,900.00
	ESTIMATE TOTAL			\$5,136.20

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the insurance company.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanphie 92495747
wp' 27/12/21 C Spr
pp Rising before part
23 days
Tanphie @ 21/12/21

Date/Time: 27.12.2021 10:49

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4155774

JC NO305499191

OMER

S COMFORT TRANSPORTATION PTE LTD
OMER NO 7010045
LESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

OUNT CARD NO.

REGN NO: SHB6353L	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 27.12.2021 08:40
YR OF MANU 30.04.2019	TARGET DATE
CHASSIS CODE KMHC851CVKU146269	COMPLETION DATE/TIME


JOB DESCRIPTION

Accident Date: 24.12.2021
ATURE: 3P 24.12.2021

NO
00010

LABOR CODE
PB

DESCRIPTION
PANEL BEATING-SHB6353L



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

to: SHB6353L LIMITS

Vehicle No.: SHB6353L

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard