



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:WINNIE			Ref: CC4/ASM21013185/Uga3q2 Date: 20/04/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SGG 8568G	Veh. Inspected	SML 1943E
	Policy No.	GA038249	Coverage (\$)	0.00
	Claim No.	S1M03P2J	Excess (\$)	0.00
	Assign From		Assign Date	28/12/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	NISSAN SYLPHY (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	MNTBBAB17Z0035225	Colour	SILVER
	Odometer	47520 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/60 R16	YOKOHAMA	8 mm
	L/H Front Tyre	195/60 R16	YOKOHAMA	8 mm
	R/H Rear Tyre	195/60 R16	YOKOHAMA	8 mm
	L/H Rear Tyre	195/60 R16	YOKOHAMA	8 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	21/12/2021	Inspection Date	28/12/2021
	Survey held at	ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	