

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJM 5413Y

at Workshop m/s Soon Sen

of _____

Insured: SKW 5905E

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$43k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 15 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: 027 615

Veh No: SJM 5413Y Yr Regn: 08/01/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Toyota Proace c.c 1497

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 136007 T/Radio: Insured / Std / NI / NA

Eng/No: MR053H49305095415

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or gane/ender

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 25/12/21 D.O.I. 28/12/21

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body & The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Completed 07-01-2025 LTA \$18302 net \$24698

14/1/22 L/S \$10,500 informed consent

red 14733.50;58%

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 15

1)

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: : Site Insp (\$)

Transportation:

Report Format :

: Interview (\$)

____ S + RS, ____ SI

Lump Sum / I.B.I. (\$) _____)

: Tech. Invs (\$)

) Photos

: Weekend (\$)

) Others

TOTAL

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

ECICS LIMITED

10, Eunos Rd 8, #09-04A

Singapore Post Centre

S,pore 408600

Accident date:25/12/2021

Date:27/12/2021

*not allowed
all
2/38 10,500/
15 days
28/12/21*

Estimate cost to repair vel: SJM 5413Y (Toyota Vios) claims under vel: SKW 5905E.

1pce rear bumper	\$ 407.50	cut/trim ✓
1pce rear bumper side holder	92.30	cut ✓
10pcs rear bumper inner clips@\$ 5	50.00	new ✓
1pce tail lamp right	357.20	11 X
1pce right rear fender	804.80	3.0.5.00 ✓
1pce rear windscreen outer rubber	74.50	new ✓
1pce rear windscreen inner sealant	120.00	new 40 s/w
1set rear windscreen tape form	54.10	new 30 s/w
1pce right rear wheel housing	422.50	2 X
1set sport rim	1,500.00	ols cut 2 pcs 600 s/w
1set rear shock absorber	226.60	11 X
1pce rear fender inner shield	59.20	11 X
1pce right rocket panel	360.10	2 X
1pce right rear door	684.30	3.0.5.00 ✓
1pce right rear door top side sticker	43.50	new ✓
1pce right rear door protector	138.80	cut ✓
1pce right rear door regulator	308.50	191.20 BEAT ✓
1pce right rear door motor	632.20	450 JM ✓
1pce right rear door whether strip	157.70	trim/new ✓
1pce right rear door inner channel	171.50	new ✓
1pce right rear door trim cover board	525.10 649.30	trim ✓
2pcs right rear door hinges@\$ 75.40	150.80	BEAT ✓
1pce right rear door top outer moulding	62.10	new ✓
1pce right rear door channel rubber	120.10	11 X
1pce right front door	879.20	3.0.5.00 ✓
1pce right front door top side sticker	43.50	new Page1

4926.8

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

ECICS LIMITED

10, Eunost Rd 8, #09-04A

Singapore Post Centre

S,pore 408600

Accident date:25/12/2021

Date:27/12/2021

Estimate cost to repair vel: SJM 5413Y (Toyota Vios) claims under vel: SKW 5905E.

1pce right front door lock	\$ 415.40	JM ✓	Page2
1pce right front door lock catch	39.10	17X	
1pce right front door handed	62.60	11X	
1pce right front door protector	149.20	Best ✓	
2pcs right front door hinges@\$75.40	150.80	Best ✓	
1pce right front regulator	191.20	Best ✓	
1pce right front door motor	450 682.20 450	JM ✓	
1pce right front door inner channel	171.50	11X	
1pce right front door inner channel rubber	120.10	11X	
1pce right front door whether strip	157.50	Torn / 11 ✓	
1pce right front door top outer moulding	92.20	CU ✓	
1pce right front door trim cover board	588.10 749.90	Torn ✓	
1pce right front door side mirror	580.10 589.70	520 ✓	
1pce centre door pillar O/S	394.90	DD ✓	
1pce front windscreen outer rubber	95.90	11 X	
1pce front windscreen inner sealant	120.00	11 X	
1set front windscreen tape form	64.50	11 X	
1pce front right fender	581.10 630.10	2.5 ✓	
1pce front right fender inner shield	38.40	11 ✓	
10pcs front right fender inner shield clips@\$5	50.00	11 ✓	
1pce front fender vvti plate O/S	38.40	11 ✓	
1pce front fender top side rubber O/S	26.40	CU ✓	
1pce front wheel housing O/S	520.50	R X	
1pce front shock absorber O/S	665.00	Best X	
1pce front knuckle arm O/S	442.60	Best ✓	
1pce front knuckle arm bearing O/S	119.40	Damaged ✓	

SOON SAN MOTOR TRADING

Bk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

ECICS LIMITED

10, Eunos Rd 8, #09-04A

Singapore Post Centre


S,pore 408600

Accident date:25/12/2021

Date:27/12/2021

Estimate cost to repair vel: SJM 5413Y (Toyota Vios) claims under vel: SKW 5905E.

1pce front lower arm 015	600.50	\$ 792.30	Best ✓
1pce steering rack & pinion		1,373.30	17X
1pce drive shaft 015		1,463.70	17X
1pce bonnet		542.50	17X
2pcs headlamps@\$407.20		814.40	015 17X 17C
1pce front bumper		407.20	7.5 ✓
1pce front bumper side holder		54.70	one ✓
10pcs front bumper inner clips@\$5		50.00	MAX ✓
1pce support panel		788.60	12X
1pce front grille		350.30	17X
1pce front door glass		443.20	17X
		\$ 22,898.00	
Less 25%		5,724.50	
		17,173.50	
2pcs front & rear tyer @\$150		300.00	82X
1set door vision (assessor)		100.00	new 80 s/n
To towing		80.00	✓
To rustproof		200.00	120
To focus headlamp & wiring		100.00	30
To dismantle/renew front & rear undercarriage		450.00	17 only 150
To remove/refit rear windscreen		140.00	120
To remove/refit front windscreen		140.00	MAX
To dismantle/renew both door		300.00	120
To remove/refit interior to effect repair		150.00	80
To remove/refit engine to effect repair		300.00	MAX
To remove/refit dashboard		400.00	MAX



PEOPLES AUTO TRADING
 BLK 3007 UBI ROAD 1 #01-400
 TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER FIRST NAME	CASH	DATE	Dec 29, 2021 10:57:46 AM
LICENSE NO.	SJM 5413 Y		
MILEAGE	136008		
MAKE	CUSTOM	MODEL	TOYOTA VIOS (P93)
NOTES			

Front Wheel	SPECS				DIAGNOSIS				ADJUSTMEN			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-2.10	0.00	2.10			-9.00				-7.70		
PARTIAL TOE	-1.00	0.00	1.00		-6.40		-2.60		-0.80		-6.80	
SET BACK	---	---	---			0°02"				0°02"		
CAMBER	-0°58"	-0°12"	0°30"		-0°24"		* -1°00" 0°34"		-0°32"		* -1°08" 0°34"	
CASTER	3°30"	4°30"	5°30"		4°54"		4°36" 0°16"		4°54"		4°36" 0°16"	
KING-PIN	---	---	---		11°48"		11°18" 0°28"		11°48"		11°18" 0°28"	
INCL.ANGLE	---	---	---		11°22"		10°18"		11°14"		10°10"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel	SPECS				DIAGNOSIS				ADJUSTMEN			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	---	---	---			4.90				4.90		
PARTIAL TOE	---	---	---		4.20		0.70		4.20		0.70	
SET BACK	---	---	---			0°10"				0°10"		
CAMBER	---	---	---		-1°02"		-1°10" 0°06"		-1°02"		-1°10" 0°06"	
THRUST ANGLE	-0°08"	0.00	0°08"			0°16"				0°16"		



Reg No: 52977287 J

CASH SALE/WORK ORDER

迅速拖車服務

SPEEDWAY RECOVERY SERVICE

Singapore Post Centre Post Office P.O. Box 201 Singapore 914007

Tel: 6841 0080

No: E 20050

Date: 25/12/21

Name/Company Cash

Vehicle No. SJM 54139 Model Vios

From Jim Lhak

To UBI T.W

Remarks _____

Time: : - : - :

- Jump Start
- Tyre Replacement
- Accident/Breakdown
- Multi/Basement
- With Load/Cargo Box
- King Dolly
- Transport Charge
- Low Body Kit
- Door Opening Service
- Crane Up/Winch Out
- Collect Doc/Key
- Repo Payment
- Trips

Amount \$ 50/-

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

Tow Truck [Signature]

24 HRS TOWING SERVICE
6841 0080

www.speedwayrecovery.com
Email: speedwaytowing@gmail.com

Received By Pd.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	256Z
Vehicle Details	
Vehicle No.:	SJM5413Y
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Dec 2021
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	1NZX851346
Chassis No.:	MR053HY9305095415
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$11,900.00
Original Registration Date:	08 Jan 2009
First Registration Date:	08 Jan 2009
Transfer Count:	2
Actual ARF Paid:	\$1,115.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 Jan 2029
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$26,047.00
COE Rebate Amount:	\$18,302.00
Total Rebate Amount:	\$18,302.00

The information contained herein is correct as at 28 Dec 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	27/12/2021 12:46 (SGT)
Date of Accident	25/12/2021 11:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	LORONG MARICAN / JALAN ISHAK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM5413Y
-----------------------------	----------

INSURED/POLICYHOLDER

is company?	No
Name Of Registered Owner	CHONG MEE YIN
NRIC No	S1429256Z
Email Address	JOONJOONWEIWEI@GMAIL.COM
Mobile Phone No	(Phone) +65-98159582
Alternative Phone No	+65-97502220

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Vios
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1500

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5122039646
Cover Note Number	07/07/2022 - 06/05/2022

SKETCH PLAN


Vehicle Category	Private car
Name of Driver	ZHANG JIAYANG, MICHAEL
NRIC No	S9040973E
Contact Number	(Phone) +65-91278855
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	FRONT PORTION
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	TAN JOON-WEI, BERNARD
Gender	Male
Phone No	(Phone) +65-97502220
Address	BLK 111 LENGKONG TIGA #07-245
Address Complement	-
Post Code	410111
Approximate Age Years Old	-
Injuries Sustained	NECK, HEADACHE
Injured person in which vehicle?	SJM5413Y
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN



REFER TO POLICE REPORT

DECLARATION

We declare the foregoing particulars are true in every respect.

27/12/2021 12:38

Policyholder's Signature
Date & Time:

Driver's Signature (if driver is not the policyholder)
Date & Time:

27/12/2021 12:38

Reporting Centre Personnel's Signature
Name: Chen Junliang
NRIC/ Fin No: S990765



**SINGAPORE
POLICE FORCE**



T/20211225/2040

Police Station Of Origin:
Kampong Kembangan NPP
112 Lengkong Tiga #01-215 SINGAPORE
410112
Tel No: 1800-7489999

4 of 4

Report No. T/20211225/2040

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan


IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature of Officer Recording The Report
G /
Sgt 2 SARVESHVERAN S/O
JAGATHESAN 

Signature Of Informant:


Signature Of Interpreter:
Not applicable

Date/Time:
25/12/2021 14:50

Officer In Charge Of Case:

SEANG YI TING, STEPHANIE 
Contact No.: 65476414

Classification Of Case:

Authentication Stamp
NP168 SIGNATURE