

ASS REC. BY: TGM

REF:

CS/MSG 210 13198/Bvf3

Veron

ASSIGNMENT

From: _____ Date: 28/12/2021

Estimated Cost: _____

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: WC 37394

at Workshop m/s Bifrost Auto

of Skaki Bt Ave 4 Premier # 01-49

Insured: SLR 6790B

Policy No. 30001622865

Claims No. 267135


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 38,000/2

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: WC 37394 Yr Regn: 14/10/2010

Type: M.Car / M.Cycle / Bus / Van / ☒ Car / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Suzuki CYH525 c.c. 15,681

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 391353 T/Radio: Insured / Std / NI / NA

Eng/No: 6WGA1412300

C/No: JALCYH525A7000021

Gen. Cond: Good / Fair / ~~Bad~~ / BurntSteering: ~~Good~~ / Jammed / Leaked / Burnt orBroke: ~~Good~~ / Jammed / Leaked / Burnt orModi: ☒ S/Rim / STD A/Rim or

Tyre Size: F: 295/80/22.5

R: 295/80/22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Fire max

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 18/12/2021

D.O.I. 28/12/2021

Survey held at Bifrost

Des. of Damages: Frt / ~~Bad~~ / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range 9000/2 - 10,000/2

Recommended COR is LS \$9200.00 TGM Mia

31/8/22 Submit LS \$8000 (un-confirmed)

MV 38,000/2

PV 9656.00

NV 28344/2

TGM Mia

10/1/2022

Date/Time, File Pass to?

☐ : Preli. Report

D)

☐ : Final Report

Date/Time, File Return to?

31/8/22-typist

Days Of Repair: 8

Resurvey No. of Trip: _____

Add Fee:

☐ Site Insp (\$ 1)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS \$1

Photos

Others

TOTAL

Report Format: _____

Lump Sum/ L.B.I. /

AUTO PTE LTD
 9 KAKI BUKIT #01-49 SINGAPORE 415875
 4457
 -65 64524584
 :g No: 201929175W

Estimate

Vehicle No: WC3739U
 Model and make: ISUZU / CYH52S
 Chassis:

Qty Spare parts

List price

- 1 Rear axle housing
- 1 Rear axle housing shaft gasket
- 1 Rear axle housing shaft
- 1 Rear axle housing shaft oil seal (inner)
- 1 Rear axle housing shaft oil seal (outer)
- 1 Rear RH wheel bearing (inner)
- 1 Rear RH wheel bearing (outer)
- 1 Rear RH wheel bearing retainer oil seal
- 1 Rear RH wheel bearing lock plate
- 1 Rear RH wheel bearing lock nut
- 1 Rear RH wheel bearing hub
- 1 Rear RH leaf spring
- 2 Rear RH leaf spring bush
- 1 Rear RH leaf spring shackle (front)
- 1 Rear RH leaf spring shackle (rear)
- 2 Rear RH leaf spring centre U-bolt
- 4 Rear RH leaf spring centre U-bolt lock nut
- 1 Rear RH shock absorber
- 1 Torjan carrier assy
- 2 Rear RH tor rod
- 1 Rear RH brake vaccum pump
- 2 Rear RH brake vaccum pump high pressure hoses

\$	2000.00	11,350.50	BT
\$		✓22.30	NECV
\$		2,676.00	NDX
\$		✓31.80	
\$		✓22.70	NECV
\$	140.00	345.80	JMV
\$		✓120.78	
\$		✓260.40	NECV
\$		✓22.50	NECV
\$		✓66.00	NECV
\$		1,590.00	NDX
\$		3,678.00	NDX
\$		320.70	
\$		545.80	
\$		545.80	
\$		244.00	
\$		104.00	
\$		448.00	NDX
\$		4,805.00	
\$	790.00	2,884.00	BT
\$		2,810.60	
\$		640.00	

\$	3476.48	33,534.68
-10%	\$ 347.65	3,353.47
\$	3128.83	30,181.21

Qty Spare parts

Special nett price

- 1 Rear under-run bumper
- 1 Rear under-run bumper RH bracket
- 1 Rear under-run bumper LH bracket
- 1 Rear number plate
- 1 Rear number plate lamp
- 1 RH taillamp
- 1 RH taillamp bracket
- 1 Tailamp wire harness
- 1 RH rear wheel mudgaurd
- 1 RH rear wheel mudgaurd mudflap

\$	1300.00	1,800.00	BT
\$		550.00	BT
\$		550.00	NDX
\$		70.00	
\$		155.00	NDX
\$		358.00	
\$		✓220.00	DL
\$		835.00	NNX
\$		✓1,600.00	BT
\$		✓220.00	BT

- 1 RH rear wheel mudguard bracket
- 1 Ladder assy
- 1 Ladder lower bracket
- 1 RH rear rim (outer)
- 1 RH rear tyre (outer)
- 1 RH rear rim (inner)
- 1 RH rear tyre (inner)
- 1 Gear oil
- 1 Brake fluid
- 1 Open / closed switch motor assy
- 1 Open / closed switch motor bracket

\$ 220.00	380.00	BTU
\$ 800.00	3850.00	BTU
	✓ 220.00	BTU
\$ 600.00	680.00	BTU
\$ 360.00	500.00	CUT
	680.00	NDX
\$ 360.00	500.00	CUT
\$	220.00	
\$	120.00	
\$	2250.00	NNX
\$	225.00	
<u>5800.00</u>		

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

\$ ~~2000.00~~ 2200.00 ✓

Spray painting on affected panels

\$ 600.00 1,800.00 ✓

Check wiring and lighting system

\$ 180.00

Apply rust coating chemical on affected panels

\$ 280.00

Remove and replace rear undercarriage parts to assist repair

\$ 1,600.00

Conduct and adjust wheel alignment system

\$ 350.00

Remove, reinstall, replace and re-adjust rear axle housing gears to new axle housing

\$ 750.00

Remove, check and reinstall air compressor hoses to assist repair

\$ 350.00

Remove, check and replace rear wire harness to assist repair

\$ 220.00

2600.00

Survey & Resurvey

28/12/2021

1245 hrs

Tim Min

Lump sum repair

Repair days 10

Total: \$ 54,894.21

Parts 3128.83

SN 5800.00

Labour 2600.00

11528.83

@ 20% 2305.77

9223.07

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LS 9200/2

Tim Min

10/1/2022

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	508G
Vehicle Details	
Vehicle No.:	WC3739U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Dec 2021
Vehicle Make:	ISUZU
Vehicle Model:	CYH52S
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	6WG1412300
Chassis No.:	JALCYH52SA7000021
Maximum Power Output:	-
Open Market Value:	\$106,208.00
Original Registration Date:	14 Oct 2010
First Registration Date:	14 Oct 2010
Transfer Count:	1
Actual ARF Paid:	\$5,311.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Oct 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$12,728.00
COE Rebate Amount:	\$9,656.00
Total Rebate Amount:	\$9,656.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 27 Dec 2021

OK

MV
PV
NV

9656/2

Terim Lin
10/1/2022



Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

BMW 740Li New 2015 Model, Carbon Chassis 3.0 Engine.



0-100 @ 5.6s 250km/h
Unbeatable Driving Pleasure.
Min PARF \$62k Low Depre
Dynamic Motoring [See Ad](#)

PRIME MOTOR & LEASING
(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted 20 results/page

2 vehicles



Isuzu CYH52S

Advanced Search Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Isuzu CYH52S	Any	Any	> 10 year(s) old	Any	Any	Any	Available



Isuzu CYH52S (COE till 08/2027)

\$58,888

\$10,440 /yr

27-Sep-2007

15,681 cc

-

Truck

Available

Fuel Type: Diesel

Posted: 26-Dec-2021 Tags: 2007 Isuzu CYH52S, Isuzu CYH52S, Isuzu, CYH52S

DIRECT OWNER



Isuzu CYH52S (COE till 07/2027)

\$105,800

\$19,040 /yr

14-Oct-2008

15,681 cc

-

Truck

Available

Fuel Type: Diesel

12 Wheeler Self-Loader With Auto Bridge. New Paintworks, Excellent Condition, High Trade-in. 0% Down Payment. In-House Loan Available. Call To View The Vehicle Today.

Convince Auto

Posted: 09-Dec-2021 Tags: 2008 Isuzu CYH52S, Isuzu CYH52S, Isuzu, CYH52S

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Isuzu, Isuzu Singapore, used Isuzu, used vehicles Singapore or even buy used Isuzu, Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	20/12/2021 18:07 (SGT)
Date of Accident	18/12/2021 02:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PUNGGOL COAST RD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	WC3739U
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	DIPCIE CONTRACTORS PTE.LTD.
Company Reg No	200916508G
Email Address	admin@dipcie.com
Mobile Phone No	(Phone) +65-66352155
Alternative Phone No	(Office) +65-66352155

VEHICLE PARTICULARS

Manufacturer	Isuzu
Model	CYH52S
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	15681

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5119446520-01
Cover Note Number	15/10/21-14/10/22

DRIVER

Name of Driver	CHINNAPPAN BENJAMINRAJ
Passport No/FIN	G7438039K

Occupation	Outdoor
Date Of Driving Pass	12/11/2021
Driving experience	1 MONTH
Gender	Male
Mobile Number	(Phone) +65-98951917
Alt. Phone Number	-
Email Address	admin@dipcie.com
Address	-
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER SKETCH ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR6790B
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	(Phone) +65-90616379
Address	-
Address complement	-

Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

1 VEHICLE NO: WC 37 39 U

2 INSURER CO: NTH C

3 ACCIDENT DATE & TIME: 18/12/21
5 AM

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claim process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the G24 Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claim, including the settlement of the claim; and any necessary investigations relating to the claim;
(ii) investigating the accident and/or my claim;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claim (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes and/or packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claim.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firm, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firm), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A

B

Punggol Coast Rd

B. SLR6790B

Ins. NTHU Veh No. WL3739U DoA: 18/12/21 2am

On 18/12/21 6pm I retrieved my vehicle & saw a note on my door handle (photo attached). There was damage to my vehicle.

Note: Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

() Claim Own Policy () Claim Third Party () Reporting Only
(/) Claim OB/TP at other workshop (13* A + 0 P + 0 O)