

(08/11/13) wef

ASS. REC. BY: James

REF:

CS/AM 21013200/R19/3

687F

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SBB 266R
at Workshop m/s Cycle & Carriage
of 201, Pansan Garden
Alh

Insured:

Policy No.

Claims No. 4557012697SGSum Insured: 300 Excess: 300

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 96k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SBB 266RYr Regn: 2021 / AugType: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA CERATO 1.6(CA) EX c.c. 1591Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 2639 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KNAF3416MM S10 7363Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FIRENZA

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 23/12/21D.O.I. 28/12/21

Survey held at

Cycle (AG)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 4HK

30/12/21@11.28am revert to AIG via Merimen.

30/12/21@3.43pm Kok Chong informed C/A via Merimen.

30/12/21@4.38pm Informed Kevin C/A & ex:\$300 by email.

21/01/22@5.50pm confirmed with Larry final fig \$6121.80, 3 days. (Red \$1148.40, 16%)

Date/Time, File Pass to?

☐ : Prel. ReportDays Of Repair: 3

1)

☐ : Final ReportResurvey No. of Trip: 1

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee: ☐ : Site Insp (\$): S + RS SI☐ : Interview (\$

) : Photos

☐ : Tech. Invs (\$

) : Others

☐ : Weekend (\$

)

Report Format : MER-ODLump Sum / I.B.I. (\$) 6121.80

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Mr Ang Kok Peng
	Reg No/Reg Date	SBB266R / 19/08/202
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MM5107363
	Engine No	G4FGMH703099
	Make/Model	KIA/CERATO 1.6 A EX G730
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	27/12/2021/ 10:08	BLK	282 / Kevin Leong	44431

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRTBUMPER, BODY KIT & AFFECTED AREA				400 800.00
E PNT98000 PAINT WORK ON FRT BUMPER & BODY KIT				700 1050.00
E PNT88000 REMOVE & INSTALL FRT BODY KIT				80.00
M SUNDRY TO APPLY SEALANT ON AFFECTED AREA				X 40.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRY SUNDRIES				20 40.00
M LAMP ASSY-HEAD, LH <i>scr</i>	1.00	1219.00	20.00	975.20
M COVER-FR BUMPER <i>cr</i>	1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER <i>cr</i>	1.00	262.00	20.00	209.60
M MOULDING-FRONT BUMPER, LH <i>cr</i>	1.00	36.00	20.00	28.80
M LAMP ASSY-FRONT FOG, LH <i>scr</i>	1.00	303.00	20.00	242.40
M LAMP ASSY-SIDE REPEATER, LH <i>scr</i>	1.00	143.00	20.00	114.40
M ABSORBER-FRONT BUMPER ENERGY ?	1.00	84.00	20.00	67.20
M AIR DUCT-FR BUMPER, LH ?	1.00	14.00	20.00	11.20
M BRACKET-FR BUMPER UPR SIDE MTG ?	1.00	22.00	20.00	17.60
M NEW K3 2020 BODYKIT MIS	1.00	1721.00	00.00	1721.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Acknowledged by Repairer

Signature:

Date:

 7% GST on **Nett** 6,053.80
 423.77
Total Payable 6,477.57

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	24/12/2021 11:50 (SGT)
Date of Accident	23/12/2021 18:48 (SGT)
Exact Location of Accident	6 Raffles Blvd, Marina Square, Singapore 039594
Additional Location Information	Basement Carpark
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBB266R
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ANG KOK PENG
NRIC No	SXXXX687F
Email Address	steven@changi-light.com.sg
Mobile Phone No	(Phone) +65-96166886
Alternative Phone No	(Home) +65-96166886

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	EX
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1591

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	-
Cover Note Number	7210093332

DRIVER

Name of Driver	ANG KOK PENG
NRIC No	SXXXX687F

Date Of Birth	05/10/1962
Occupation	Indoor
Date Of Driving Pass	20/12/1982
Driving experience	39 YEARS
Gender	Male
Mobile Number	(Phone) +65-96166886
Alt. Phone Number	(Home) +65-96166886
Email Address	steven@changli-light.com.sg
Address	49 Lentor Grove Singapore
Address complement	-
Postcode	789215
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	CHUA GUEK HOON
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO THE ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMY989L
Vehicle Manufacturer	Mercedes
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	Blue
Vehicle Category	Private car

Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

-
- (Phone) +65-96649010
-
-
-
-
-
-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

VEHICLE A = SBB266R
VEHICLE B = SMY989L

Describe Circumstances of the Accident

ON 23.12.21 at 6.48pm While Driving inside
MARINA SQUARE Carpark looking For parking lot.

suddenly I collide with A vehicle CAR plate number SMY989L
Nobody Was injured.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

[Signature] 24/12/21

11.00AM

Driver's Signature (If driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel

[Signature]

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	687F
Vehicle No.:	SBB264R
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Dec 2021
Vehicle Make:	KIA
Vehicle Model:	CERATO 1.6(A) EX
Primary Colour:	White
Manufacturing Year:	2021
Engine No.:	G4FGMH703099
Chassis No.:	KNAF3416MM5107363
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$14,606.00
Original Registration Date:	19 Aug 2021
First Registration Date:	19 Aug 2021
Transfer Count:	0
Actual ARF Paid:	\$14,606.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Aug 2031
PARF Rebate Amount:	\$10,954.00
COE Expiry Date:	18 Aug 2031
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,189.00
COE Rebate Amount:	\$43,549.00
Total Rebate Amount:	\$54,503.00

The information contained herein is correct as at 29 Dec 2021

OK

Kia Cerato 1.6A EX

Overview

Financial

Accessories

Similar

Research

Photos

Map



Price

\$86,800

Depreciation

\$9,200 /yr

[View models with similar depreciation](#)

Reg Date

14-Aug-2020

(8yrs 7mths 15days COE left)

Mileage

38,000 km (27.6k /yr)

Manufactured

2019

Road Tax

\$738 /yr

Transmission

Auto

Dereg Value

\$39,632 as of today ([change](#))

OMV

\$14,882

COE

\$33,000

ARF

\$14,882

Engine Cap

1,591 cc

Power

93.8 kW (125 bhp)

Curb Weight

1,287 kg

No. of Owners

1