

|   |        |      |             |
|---|--------|------|-------------|
| 1 | of 2 ? | 100% | Find   Next |
|---|--------|------|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|                                                                                                                                        |                                                                                           |                 |                          |  |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|-----------------|--------------------------|--|
| <b>Affiliated to Federation Internationale Des Experts En Automobile</b>                                                               |                                                                                           |                 |                          |  |
| SINGAPORE CIVIL DEFENCE FORCE (MHA05)                                                                                                  |                                                                                           |                 | Ref: CS/SCD21013214/Kqf3 |  |
| 91 UBI AVE 4                                                                                                                           |                                                                                           |                 | Date: 28/12/2021         |  |
| SINGAPORE 408827                                                                                                                       |                                                                                           |                 |                          |  |
| SINGAPORE 408827                                                                                                                       |                                                                                           |                 | Code: SCD                |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                           |                 |                          |  |
| Insured Veh.                                                                                                                           | YP 3530L                                                                                  | Veh. Inspected  | SLT 1375P                |  |
| Policy No.                                                                                                                             |                                                                                           | Coverage (\$)   | 0.00                     |  |
| Claim No.                                                                                                                              |                                                                                           | Excess (\$)     | 0.00                     |  |
| Assign From                                                                                                                            | SUSAN QUEH                                                                                | Assign Date     | 28/12/2021               |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                           |                 |                          |  |
| Make & Model                                                                                                                           | c.c                                                                                       |                 | 0                        |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                    | Year of Reg.    |                          |  |
| Chassis No.                                                                                                                            | Colour                                                                                    |                 |                          |  |
| Odometer                                                                                                                               | -                                                                                         | Steering        |                          |  |
| Brakes                                                                                                                                 | Modification                                                                              |                 |                          |  |
| General                                                                                                                                |                                                                                           |                 |                          |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                           |                 |                          |  |
|                                                                                                                                        | Size                                                                                      | Make            | Balance                  |  |
| R/H Front Tyre                                                                                                                         |                                                                                           |                 | mm                       |  |
| L/H Front Tyre                                                                                                                         |                                                                                           |                 | mm                       |  |
| R/H Rear Tyre                                                                                                                          |                                                                                           |                 | mm                       |  |
| L/H Rear Tyre                                                                                                                          |                                                                                           |                 | mm                       |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                           |                 |                          |  |
|                                                                                                                                        |                                                                                           |                 |                          |  |
| <b>5. General Information</b>                                                                                                          |                                                                                           |                 |                          |  |
| Accident Date                                                                                                                          | 23/12/2021                                                                                | Inspection Date | 04/01/2022               |  |
| Survey held at                                                                                                                         | LIAN HER MOTORS<br>BLK 5038 ANG MO KIO INDUSTRIAL PARK 2,<br>#01-405<br>SINGAPORE 569541. |                 |                          |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                           |                 |                          |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                           |                 |                          |  |