

ASS. REC. BY: TaughnREF: CS3/191921013234/T19,83**ASSIGNMENT**

Front: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. 7975614332SG

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 938K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKS5567TYr Regn: 2015, April

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi Lancer 1.6 cc 1590Colour: white A/C: Insured / Std / NI / NASp. Reading: 170052 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JmgsRCYIAF4004130

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mmR/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

Survey held at 3 motorworks

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

04/01/22 Submit DAR.

Date/Time, File Pass to?

☐ : Preli. Report1) 04/01 Typist☐ : Final Report

Date/Time, File Return to?

2) _____

Rep. Format: MER-DAR

Lump Sum / L.B. (\$) _____

Days Of Repair: 4Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

SUS5567T

- Frt Fender LH bt ✓
- Frt Fender signal light era ✓
- Frt LH wing Mirror assy bro ✓
- Frt LH Door ddt ✓
- Frt bumper R ✓
- Frt LH fender inner shield de ✓
- Frt LH headlamp uc ?

04 days