Surveyor:

REF: CS1/LPM21013243/Uvf3

Special Instruction:

L/SUM : $ 8050.00

Third Parties:

Claimant:

Surveyor:

Workshop: Fastech Auto Pte Ltd

ASSIGNMENT (Office)

From (Person): ALEXANDRA NEO of LPM Date/Time: 28/12/2021 6:10 PM

Estimated Cost: Bill to:

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SGT 6120J Insured: BJW 390

at Workshop m/s FASTECH AUTO PTE LTD Tel: 67452063/67467158/67417244

of 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883

Policy No: Claim No: 20/21/21/VC10/330855

Sum Insured: Excess:

Make of Veh: D.O.A. 11/03/2021

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle **IN / OUT**

Date/Time: **Confirmed with** **Final Fig** , days (Red $ / %; Original 5 days)

Date/Time: 30/12/21 **Submit Final Fig** LS $5200 , 4 days (Red $ 2850 / 35 %; Original 5 days)

Date/Time	Action/Instruction
	SGT 6120J- X
	BJW 390- X

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/ Evaluated by:

Fee Charged:	*Date:*
Basic & Add	
Transport	
Photos	
Others	
Total	

1) Date/Time File Pass to 2) Date/Time File Return to

3) Date/Time File Pass to 4) Date/Time File Return to

5) Date/Time File Pass to 6) Date/Time File Return to