



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21013250/Aqf3n2 Date: 16/03/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGQ 9463R	Veh. Inspected	SMQ 2507Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10013123/EE	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	28/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN GOLF GTI	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WVWZZZAUZFW241973	Colour	WHITE	
Odometer	79989 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	FALKEN	6 mm	
L/H Front Tyre	225/40 R18	FALKEN	6 mm	
R/H Rear Tyre	225/40 R18	FALKEN	6 mm	
L/H Rear Tyre	225/40 R18	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/12/2021	Inspection Date	29/12/2021	
Survey held at	ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4, #04-01 VICOM KAKI BUKIT INSPECTION CENTER, SINGAPORE 415933.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	