

ASS. REC. BY:

REF:

TP/ CS/TP21013266/Kqc

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

09 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / SRim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.


L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Roof top or

The UIC / Chassis frame / Body Structure affected due to collision.



Date / Time

Action / Instruction

1/ GIA & Est not ready

L1 Rep @ 9500 (Red \$10126, 52%)

Date/Time, File Pass to?

☐

: Prell. Report

03/01 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

9

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Report Format:

TP

Lump Sum / +B.+ (\$

9500

RC AUTO

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722

Tel : 97619383 Email: rcauto5555@gmail.com

Reg. No. 53199168K

SLB 555 M

Date : 13.12.2021

Quantity	Description/Particular	Unit Price	Amount	
2 PCS	REAR LAMP@638	1276	00	
2 PCS	REAR LAMP LOWER BRACKET@35	70	00	
1PC	REAR LAMP PANEL(LEFT HAND)	885	00	
1 PC	REAR BUMPER REINFORCEMENT	558	00	
1 PC	REAR BOOTLID	1440	00	
1 PC	REAR BOOTLID RUBBER(180	00	
1 PC	REAR BOOTLID EMBLEM(LOGO)	41	00	
1 PC	REAR BOOTLID LOCK	356	00	
1 PC	REAR BOOTLID CATCH	38	00	
1 PC	REAR BUMPER (C63)	1450	00	
2 PCS	REAR BUMPER SIDE RETAINER@58	116	00	
1 PC	REAR PANEL(INNER)	650	00	
1PC	REAR FENDER INNER GANISH(L/H)	265	00	
2 PCS	REAR BUMPER INNER BRACKET@115	230	00	
1 PC	REAR EXHAUST	1656	00	
2 PCS	REAR EXHAUST TIP(AMG)@380	760	00	
1 PC	REAR SPARE TYRE BOARD	148	00	
1 PC	REAR PANEL GANISH(TOP)	210	00	
1 PC	REAR SPARE TYRE PANEL	330	00	

Received the above goods in good order and condition

for **RC AUTO**

Received by

E.&O.E.

Authorised Signature

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	29/11/2021 18:03 (SGT)
Date of Accident	27/11/2021 16:30 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	PIE (Changi) slip road towards KPE (ECP) & Sims Drive
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLB555M

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Goh Zhi Hao Michael Vandol
NRIC No	S8738044J
Email Address	vandol@gmail.com
Mobile Phone No	(Phone) +65-94888166
Alternative Phone No	(Home) +65-94888166

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	C180
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1600

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5104625117-03
Cover Note Number	-

DRIVER

Name of Driver	Goh Zhi Hao Michael Vandol
NRIC No	S8738044J

Date Of Birth	17/11/1987
Occupation	Indoor
Date Of Driving Pass	28/03/2007
Driving experience	14 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-94888166
Alt. Phone Number	(Home) +65-94888166
Email Address	vandol@gmail.com
Address	17 Wolskel Road
Address complement	-
Postcode	357965
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

refer attached police report.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU9161G
Vehicle Manufacturer	Honda
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver	Pot Chye Kiat
NRIC No	S1620645H
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMF7036R
Vehicle Manufacturer	Volkswagen
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	Lim Wei Jie
NRIC No	S8920975G
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	Goh Zhi Hao Michael Vandal
Gender	Male
Phone No	(Phone) +65-94888166
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SLB555M
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No

Describe Circumstances of the Accident

I WAS ON my way towards KPE (ECP) travelling along RIE (Changi) on the 27th November 2021 at around 16:30hrs.


Vehicle SLU 9161G driven by Mr. Pui Chye Kiat was ahead of me and due to another unforeseen reason, he soon broke to a complete stop on the RIE. I did not see the reason for his abrupt braking as his car is a sedan & I could not see above his vehicle as the road continues ahead.

Although vehicle SLU 9161G ahead of me braked abruptly to a complete stop, I was able to react and also bring my car to a complete stop as I had maintained sufficient following distance.

I had already brought my car to a complete stop when I felt a impact hitting me from behind. After pushing back, I realised it was the rear of SLU 9161G.

The car behind me was SLU 7036P driven by Mr. Lim Wei Jie.

Before Suddenly



(Also attach police report)

Declaration

We declare the foregoing particulars are true in every respect.