



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI21013317/Gny3q2 Date: 17/01/2023	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SFP 3688R	Veh. Inspected	SGD 9335X
Policy No.		Coverage (\$)	0.00
Claim No.	C10013140/EE	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	30/12/2021
2. Vehicle Particulars & Condition			
Make & Model	KIA CERATO 1.6	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KNAF3416MK5019507	Colour	WHITE
Odometer	192557 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/40Z R18	HABILEAD	5 mm
L/H Front Tyre	235/40Z R18	HABILEAD	5 mm
R/H Rear Tyre	235/40Z R18	HABILEAD	5 mm
L/H Rear Tyre	235/40Z R18	HABILEAD	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/12/2021	Inspection Date	30/12/2021
Survey held at	SR AUTOWORKS PTE LTD 8 KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	